

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTFORM APPROVED  
OMB No. 1004-0135  
Expires: January 31, 2004**SUNDRY NOTICES AND REPORTS ON WELLS**  
**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**

5. Lease Serial No.

NMNM-106717

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

SF 17 Federal Com #1

9. API Well No.

30-025-36345

10. Field and Pool, or Exploratory Area

Lusk Strawn

11. County or Parish, State

Lea County, NM

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Mewbourne Oil Company 14744

3a. Address

PO Box 5270 Hobbs, NM 88240

3b. Phone No. (include area code)

505-393-5905

4. Location of Well (Footage, Sec., T, R., M., or Survey Description)

1975 FNL &amp; 1422' FEL, Unit P Sec 17-T18S-R32E

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

## TYPE OF SUBMISSION

## TYPE OF ACTION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☒ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other Recomplete Strawn

3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

01/31/04...Set blanking plug in packer @ 12652'. Spot 20' of sand on top of packer to temporally isolate Morrow perfs. POOH.

02/01/04...RIH with 2 7/8" tbg to 11404'. Spot 1000 gals 15% HCl. Perforate Lusk Strawn perfs @ 11441'-528' (51', 204 total holes, 0.24' EHD).

Break down perfs and swab test.

02/06/04...Acidized with 5000 gals 20% HCl and ball sealers. Swab test.

02/17/04...Acidized with 15000 gals 20% HCl and 18000 gals gelled water. Swab test.

03/06/04...RIH w/tbg and rods. Put well on pump. PWOL.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

NM Young

Title Hobbs District Manager

Signature

Date 03/26/04

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**Approved by (Signature) SGD.) DAVID F. GLASS

Name

(Printed/Typed)

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Date

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Continued on next page)

2A Lusk Morrow North