Form 3160-5 (August 1999)

New Mexico Oil Conservation Division, District FORM APPROVED
UNITED STATES 1625 N. French Drive
DEPARTMENT OF THE INTERIOR Hobbs, NM 88240

BUREAU OF LAND MANAGEMENT 160 S. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter ar abandoned well. Use Form 3160-3 (APD) for such proposals.	Do i	o not u	se this	form	for propo	sals to	drill or	to re-enter ar
---	------	---------	---------	------	-----------	---------	----------	----------------

C TCT-Jim Attaur. TO 1 37	
NMNM106916	
5. Lease Serial No.	*.

	vell. Use Form 3160-3 (A	PV) for suc	n proposa:	S.	" -	maan, Anot	tee or Tribe Name	
SUBMIT IN TF	RIPLICATE - Other ins	tructions o	on reverse	side	7. If	Unit or CA/A	Agreement, Name as	nd/or No.
1. Type of Well		<del></del>		- A .,,,,,,,,				
Oil Well Gas Well	Other Salt Water	r Dispos	al		8. V	Vell Name and	d No	
. Name of Operator							on '31' Fe	deral
Echo Production,	Inc.				· ·	PI Well No.		
a. Address	h	3b. Pho	ne No. (includ	e area code)	3	0-025-3	2093	
PO Box 1210, Gral			549-32	92	10. F	ield and Pool	or Exploratory Are	2 296
Location of Well (Footage, Sec. 660' FSL & 660' ]	c., T., R., M., or Survey Descripti	ion)			3	WD:	Bell Car	
Section 31 T22S					i i	ounty or Pari	•	1 -
50001000 51 1225 1	KJZE			10 m	I	ea Co.,	, NM	
12. CHECK AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATU	RE OF NOTIC	E, REPOR	T, OR OTH	HER DATA	·
TYPE OF SUBMISSION				PE OF ACTION				
	Acidize	Deeper		Production	(Start/Resum	a) D 7	Water Shut-Off	····
Notice of Intent	☐ Alter Casing		re Treat	Reclamatic	.*	·	Water Snut-Off Well Integrity	
Subsequent Report	Casing Repair	_	Construction	Recomplet			<sub>Other</sub> re-entr	v
	Change Plans	Plug ar	nd Abandon	Temporari		`		
Final Abandonment Notice	Convert to Injection	Plug B		Water Dis				
to 500 ps								
2/17/04 Perforate gals.	4884-90', 4906-3	2', 5060	) <b>-90',</b> 5	379-5404'	and 54	56-96'.	Acidize v	v∕ 3000
2/17/04 Perforate gals. 2/19/04 Ran 2 7/8"	4884-90', 4906-3	2', 5060 ing and	)-90', 5 Full Bo	379-5404'	and 54	56-96'. 2' Set	Acidize v	v∕ 300€
2/17/04 Perforate gals. 2/19/04 Ran 2 7/8"	1. 4884-90', 4906-3 ' Salta lined tub	2', 5060 ing and	)-90', 5 Full Bo	379-5404'	and 54	56-96'. 2'. Set tallati	Acidize v packer ar	w/ 3000
2/17/04 Perforate gals. 2/19/04 Ran 2 7/8"	1. 4884-90', 4906-3 ' Salta lined tub	2', 5060 ing and	)-90', 5 Full Bo	379-5404'	and 54	56-96'. 2'. Set tallati	Acidize v	w/ 3000
2/17/04 Perforate gals. 2/19/04 Ran 2 7/8"	1. 4884-90', 4906-3 ' Salta lined tub	2', 5060 ing and	)-90', 5 Full Bo	379-5404'	and 54	56-96'. 2'. Set tallati	Acidize v packer ar	w/ 3000
2/17/04 Perforate gals. 2/19/04 Ran 2 7/8"	1. 4884-90', 4906-3 ' Salta lined tub	2', 5060 ing and	)-90', 5 Full Bo	379-5404'	and 54	56-96'.  2'. Settallati  ACCEP	Acidize v packer ar on.	v/ 3000
2/17/04 Perforate gals. 2/19/04 Ran 2 7/8" casing to	1, 4884-90', 4906-3 'Salta lined tub 500 psi for ½ ho	2', 5060 ing and	)-90', 5 Full Bo	379-5404'	and 54	56-96'.  2'. Settallati  ACCEP	Acidize v packer ar	v/ 3000
2/17/04 Perforate gals. 2/19/04 Ran 2 7/8" casing to	1, 4884-90', 4906-3 'Salta lined tub 500 psi for ½ ho	2', 5060 ing and	Full Bo	379-5404' ere packer tank batt	and 54 to 484 ery ins	56-96'.  2'. Settallati  ACCEP	Acidize v packer ar on. TED FOR R ARY GOURIE	v/ 3000
2/17/04 Perforate gals. 2/19/04 Ran 2 7/8" casing to  Thereby certify that the foregoin Name (Printed/Typed)  Tom Golden	4884-90', 4906-3 'Salta lined tub 500 psi for ½ ho	2', 5060 ing and	Full Bo	erations	and 54 to 484 ery ins	56-96'.  2'. Settallati  ACCEP	Acidize v packer ar on. TED FOR R ARY GOURLE OLEUMENGE	v/ 3000
2/17/04 Perforate gals. 2/19/04 Ran 2 7/8" casing to	1. 4884-90', 4906-3 'Salta lined tub 500 psi for ½ ho	2', 5060 ing and ur. Wait	Full Bo ing on	erations	and 54 to 484 ery ins	56-96'.  2'. Settallati  ACCEP	Acidize v packer ar on. TED FOR R ARY GOURLE OLEUMENGE	v/ 3000
2/17/04 Perforate gals. 2/19/04 Ran 2 7/8" casing to  Thereby certify that the foregoin Name (Printed/Typed)  Tom Golden	4884-90', 4906-3 'Salta lined tub 500 psi for ½ ho	2', 5060 ing and ur. Wait	Full Bo ing on	erations	and 54 to 484 ery ins	Settallati ACCEP	Acidize v packer ar on. TED FOR R ARY GOURLE OLEUMENGE	v/ 3000
2/17/04 Perforate gals. 2/19/04 Ran 2 7/8" casing to  Thereby certify that the foregoin Name (Printed/Typed)  Tom Golden  Signature Tow Joke	1. 4884-90', 4906-3 'Salta lined tub 500 psi for ½ ho  THIS SPACE	2', 5060 ing and ur. Wait	Full Bo ing on	erations 3/2/04	and 54 to 484 ery ins	Set tallati  ACCEP  M  GA  PETRI	Acidize v packer ar on. TED FOR R ARY GOURLE OLEUMENGE	v/ 3000
2/17/04 Perforate gals. 2/19/04 Ran 2 7/8" casing to  I hereby certify that the foregoin Name (Printed/Typed)  Tom Golden  Signature	1.  4884-90', 4906-3  Salta lined tub 500 psi for ½ ho  THIS SPACE  Approval of this notice of this notice.	2', 5060 ing and ur. Wait	Full Boting on  Title Op Date  RAL OR ST	erations 3/2/04  ATE OFFICE	and 54 to 484 ery ins	Settallati ACCEP	Acidize v packer ar on. TED FOR R ARY GOURLE OLEUMENGE	v/ 3000

