

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06935
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	W.T. MCCOMACK
8. Well No.	6
9. Pool Name or Wildcat	PENROSE SKELLY GRAYBURG
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3467' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMITS
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator CHEVRON USA INC
3. Address of Operator 15 SMITH ROAD, MIDLAND, TX 79705	4. Well Location Unit Letter <u>J</u> : <u>1980'</u> Feet From The <u>SOUTH</u> Line and <u>1980'</u> Feet From The <u>EAST</u> Line Section <u>32</u> Township <u>21-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: DRILL DEEPER IN GRAYBURG ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-31-04: MIRU KEY #462. REL TAC.
4-01-04: TIH & TAG @ 3771. RU FOAM AIR UNIT. C/O FILL DN TO 3780. DRILL NEW 6 1/4" OPEN HOLE FR 3780-3812.
4-02-04: TIH W/2 7/8" TBG & TAG @ 4797. WASH FILL FR 3797-3812. DRILL NEW HOLE FR 3812-3893. PULL UP IN CSG @ 3610.
4-05-04: TAG FILL @ 3888. C/O FILL DN TO 3893. DRILL NEW 6 1/4" HOLE FR 3893-3950.
4-06-04: TIH W/PK & SET @ 3567. ACIDIZE GRAYBURG O.H. FR 3626-3950 W/4500 GALS 15% ANTI-SLUDGE HCL. RU SWAB. 3 HR TEST. REL PKR @ 3567. TAG SALT FILL @ 3935. PMP 120 BBLs 8.6 PPG CBW DN TBG. DISSOLVE SALT DN TO 3946.
4-07-04: RU SWAB. TAG @ 3946. PU FRAC PKR & SET @ 3537. NU FRAC TREE.
4-08-04: FRAC GRAYBURG O.H. FR 3626-3950 W/66,000 GALS YF135 & SAND.
4-09-04: TAG SAND @ 3720. PUH INTO CSG @ 3621.
4-12-04: 9 HR SWAB TEST.
4-13-04: TAG @ 3720. C/O FILL DN TO 3950.
4-14-04: TAG TD @ 3950. TIH W/SUB PMP. RIG DOWN. TURN WELL OVER TO PRODUCTION TO HOOK UP FLOWLINE & ELECTRICITY.

FINAL REPORT WAIT ON TEST

4-18-04: ON 24 HR OPT. PUMPING 19 OIL, 341 GAS, & 1350 WATER.

GOR-17947
TBG PRESS - 180#
CSG PRESS - 90#
GRAV-37.9



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Leake TITLE Regulatory Specialist DATE 4/20/2004
TYPE OR PRINT NAME Denise Leake Telephone No. 915-687-7375

(This space for State Use)

APPROVED [Signature] TITLE PETROLEUM ENGINEER
CONDITIONS OF APPROVAL, IF ANY:

DATE

APR 26 2004