

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources  
**OIL CONSERVATION DIVISION**  
1220 S. St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO. 30 025 21644
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: State 32
8. Well No. 2
9. Pool name or Wildcat SWD Ellenburger (96103)

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Bruce A. Wilbanks Company	
3. Address of Operator c/o P.O. Box 953, Midland, TX 79702	
4. Well Location Unit Letter <u>J</u> <u>1980</u> feet from the <u>S</u> line and <u>1980</u> feet from the <u>E</u> line Section 32 Township 23S Range 38E NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT GR, etc.)	

**I 1. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENTJOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3-17-04: Notified Oil Conservation Division - Gary Wink. Moved in & rigged up Triple N Well Service. Pulling tubing out of hole. SION. OCD representative Buddy Hill on location.  
3-18-04: RIN w/production tubing, tagged PBTD @ 9465'. Circulated hole w/mud. POOH w/tubing to 6600', pumped 25 sx Cl C cement from 6600-6350'. Pulling out of hole w/tubing. SION.  
3-19-04: Continue pulling tubing. Cut 5 1/2" casing @ 3497'. POOH w/wireline. Speared casing free. Pulled out of hole with 82 1/2 jts 5 1/2" casing. RIH w/tubing to 3547'. SD for weekend.  
3-22-04: Pumped 75 sx Cl C cement with 2% CaCl2 @ 3547'. Tagged cement @ 3256'. Pulled up to 1550' and pumped 35 sx Cl C cement from 1550-1450'. RU wireline & perforated 8 5/8" @ 531'. RIH w/8 5/8" packer to 90', loaded hole, set packer, established rate, squeezed 90 sx Cl C cement @ 531'. Well shut-in.  
3-23-04: RIH w/tbg, tagged cmt @ 505', notified OCD, pumped additional 25 sx Cl C @ 506'. Pulled up to 62' & circulated 25 sx cement to surface. Will install marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ann E. Ritchie TITLE Regulatory Agent

DATE 4-9-04

Type or print name Ann E. Ritchie

Telephone No. 432 686-688

(This space for State use)

APPROVED BY Gary W. Wink ON BEHALF OF FIELD REPRESENTATIVE II / STAFF MANAGER DATE MAY 03 2004  
Conditions of approval, if any:

Approved as to plugging of the Well Bore.  
Liability under bond is required until  
surface restoration is completed.