Submit 3 Copies to Appropriate District Office State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I	_			OIL C	DIAPEKA	AIIO	IN DIVIS	IOIA							
P.O. Вож 1980, Ноbbs, NM 88241-1980  2040 South Pache Santa Fe, New Mexico							505		WELL API N 30-025						
DISTRICT II 811 S. First Street, Astesia, NM 88210										5. Indicate Typ	e of Lease	STATE	x	FEE	
DISTRICT III 1000 Rio Bezzos Rd., Aztac, NM 87410										6. State Oil & Gas Lease No. E-2520					
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)										7. Lease Name	os Unit Agner	nent Name			
Type of Well: OIL		GAS	(FURM C-	IOI) POR SUC	CH PROPOSAL	5.)			<del> </del>						
WELL	<u> </u>	ZELL			OTHER					STATE I	1Q				
. Name of Operator		OIL C	OMPA	NY						8. Well No.	1				
3. Address of Opeza										9. Pool Name	or Wildest				-
	POS	T OFF	ICE B	OX 310, I	ROSWELL	., NEW	MEXIC	0 88202-0	310	AIRSTR	IP BONE	SPRINGS			
4. Well Location Unit Letter		P	:	960	Feet From The	SOUT	ГН	_ Line and	<del></del>	33	80 F	et From The	E	AST	_ Line
Section	26		Township		18 SOUTH	+		Range	34 EA	ST	NMPM	LEA		County	,
			•		10. Elevation (S	how wheth			·	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
11.			Chi	eck Annro	priate Bo		8' GR licate Nat	ture of No	tice Ren	ort or Ot	her Data				
• 1 .	NOTICE	OF IN			Priate DU	C IIIC	aivaic Ital					PORT OF:			
PERFORM REME	DIAL WORK	[	PLUG AND ABANDON					REMEDIAL WORK				ALTERING CA	SING		
TEMPORARILY ABANDON			CHANGE PLANS					COMMEN	MMENCE DRILLING OPNS.			PLUG AND AB	ANDONME	ENT	X
PULL OR ALTER CASING								CASING TE	ST AND CEM	ENTJOB					
OTHER:						_		OTHER:		···································	. <u>.</u>				
12. Describe Propo	osed or Compl	eted Oper	itions (Clea	zly state all perf	inent details, an LL AS FO	d give pert	tinent dates, in	duding estimate	d date of start	ing uny propos	ed work)				
					35 SXS O								وستعدد مراس		
	4: PULL	_			00 0710 0		0,00.					(22)	3031	-72	
04/21/04: SPOT 30 SXS @ 6319'-6138'.												1320		•	13.50
04/21/04: SPOT 50 SXS @ 4091'-3937' TAG.												(59°	`>	,	$-\infty$
04/21/04: SPOT 50 SXS @ 1831'-1676'.												197	25	3	ęw)
04/21/04	04/21/04: SPOT 50 SXS @ 365'-233' AND TAG.												S. C.	* '\	
04/22/04	4: SPOT	20 SX	(S @ 3	0' TO SU	RFACE.								03		*/
	INICT		<b>3037 11</b>	D. E. \$44.D	KED							000			١
INSTALL DRY HOLE MARKER. CIRCULATE 10# MUD.												15.8	181718	31314	"/
	Circ	COLAI	E 10#	MOD.											
I heseby certify that	the information	above is t	rue and com	plets to the best	of my knowledg	e and belief									
SIGNATURE -	$\Rightarrow$	$\Rightarrow$	-			TITLE	PRES	SIDENT		<del> </del>		DATE		5/3/04	<u> </u>
TYPE OR PRINT	NAME	$\overline{}$	OSEF	PH J. KEL	LY						TELEPHO	NE NO.	505-6	23-319	0
(This space for State	Use)				- 1										
APPROVED BY	$_{-}$ $\mathcal{Y}$	سو	1_ L	.ليا.ز	uk	TITLE	ac	Æ F	<b></b>			DATE	M	<u> </u>	3 20
CONDITIONS OF	APPROVAL,	FANY: (	I			-		, LETO K	EPRESEN	TATIVET	/STAFF	MANAGER	MA	Y 1	3 200

Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.