

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised June 10, 2003

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	WELL API NO. 30-025-36578
	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Pecos Production Company	6. State Oil & Gas Lease No.
3. Address of Operator 400 W. Illinois, Suite 1070, Midland, TX 79701	7. Lease Name or Unit Agreement Name New Mexico G State
4. Well Location  Unit Letter <u>O</u> : <u>450</u> feet from the <u>South</u> line and <u>1800</u> feet from the <u>East</u> line  Section <u>23</u> Township <u>21S</u> Range <u>36E</u> NMPM Lea County	8. Well Number 37
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3553' GR	9. OGRID Number 215758
	10. Pool name or Wildcat Eumont-Yates-7Rvrs-Qn-Oil

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  
**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Spud, Set Surface & Production Casing ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5/1/04 -MIRU Capstar Rig. Spud 12 1/4" hole. TD 12 1/4" hole @ 374'. Ran 8 5/8" 24# J-55 csg & set csg @ 374'. Cmt csg w/300 sxs Prem Plus + additives. Circ 56 sxs. WOC 18 hrs.  
5/2/04 -Test rams 200 / 700 psi - ok. Resume drlg 7 7/8" hole.  
5/6/04 -TD @ 3850'. Ran logs. RU csg crew & ran 5 1/2" csg & set @ 3850'.  
5/7/04 -Cmt csg w/550 sxs Interfill "C" & 150 sxs Prem Plus. Circ out 62 sxs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dora Lara TITLE Engr Asst. DATE 5-10-04

Type or print name Dora Lara E-mail address: dorab@pecosproduction.com Telephone No. 432-620-8480

(This space for State use)

APPROVED BY Gary W. Wink TITLE QC FIELD REPRESENTATIVE II / STAFF MANAGER DATE MAY 14 2004  
Conditions of approval, if any:

