

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised June 10, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> 2. Name of Operator Pecos Production Company 3. Address of Operator 400 W. Illinois, Suite 1070, Midland, TX 79701 4. Well Location Unit Letter <u>A</u> : <u>661</u> feet from the <u>North</u> line and <u>659</u> feet from the <u>East</u> line Section <u>24</u> Township <u>21S</u> Range <u>36E</u> NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3529'	WELL API NO. 30-025-35969 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name Leonard State 8. Well Number 4 9. OGRID Number 215758 10. Pool name or Wildcat Eumont-Yates-7Rvs-Qn-Oil
---	--

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐


OTHER: Spud, Set Surf & Prod Csg ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5/6/04- Spud 12 1/4" hole.

5/7/04- TD 12 1/4" hole @ 375'. Ran 8 5/8" 24# J-55 8rd STC csg & set @ 370'. Cmt csg w/300 sx Cl C + additives. Circ 17 sx to pit. WOC 18 hrs.

5/13/04- TD 7 7/8" hole @ 3968' (well TD). Ran OH logs (DL/MSL/GR/DSL/SDL). Ran 5 1/2" J-55 csg, set csg @ 3968'. Cmt csg w/875 Cl C + additives. Circ 23 sx cmt to reserve pit. ND BOP, set slips & cut csg. Rig released.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dora Lara TITLE Engr. Asst. DATE 5-14-04

Type or print name Dora Lara

E-mail address: dorab@pecosproduction.com

Telephone No. 432-620-8480

(This space for State use)

APPROVED BY Dora W. Wink

FIELD REPRESENTATIVE II / STAFF MANAGER MAY 24 2004

Conditions of approval, if any: