

DISTRICT I

P.O. Box 1980, Hobbs, NM 88241-1980

DISTRICT II

811 S. First Street, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Artesia, NM 87410

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, New Mexico 87505

WELL API NO.
30-025-26533

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
L-3556

7. Lease Name or Unit Agreement Name
Airstrip SWD System
STATE "FU"

8. Well No.
2 1

9. Pool Name or Wildcat
Airstrip Bone Spring

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL ☐ GAS ☐
WELL ☐ WELL ☒ OTHER ☐ Salt Water Disposal Well

2. Name of Operator
ELK OIL COMPANY

3. Address of Operator
POST OFFICE BOX 310, ROSWELL, NEW MEXICO 88202-0310

4. Well Location
Unit Letter E : 1700 Feet From The North Line and 660 Feet From The WEST Line
Section 25 Township 18 SOUTH Range 34 EAST NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3975' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

SEE RULE 1103 PLUG AND ABANDON WELL AS FOLLOWS:

04/22/04: SET CIBP AT 9275'
04/26/04: SPOT 35 SXS AT 6318'-6139'
04/27/04: PERFORATED AT 4054', 3903', 3800' AND 3500' - TEST TO 1200#
04/28/04: SPOT 110 SXS AT 4117'-3429' TAG
04/29/04: PULL 2783' OF 7" CASING
04/29/04: SPOT 45 SXS AT 2829'-2765' TAG
04/30/04: SPOT 30 SXS AT 2765'-2675'
04/30/04: SPOT 40 SXS AT 1822'-1702'
04/30/04: SPOT 40 SXS AT 377'-252' AND TAG
05/03/04: SPOT 10 SXS AT 30' TO SURFACE

INSTALL DRY HOLE MARKER. CIRCULATE 10# MUD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Joseph J. Kelly* TITLE PRESIDENT DATE 5/7/04
TYPE OR PRINT NAME JOSEPH J. KELLY TELEPHONE NO. 505-623-3190

(This space for State Use)

APPROVED BY *Mary W. Wink* TITLE OC FIELD REPRESENTATIVE II / STAFF MANAGER DATE JUN 09 2004
CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

