

DISTRICT I

1625 N. French Dr., Hobbs NM 88240

DISTRICT II

1301 W. Grand Avenue, Artesia NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec NM 87410

DISTRICT IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-35964

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
VO-6649

7. Lease Name or Unit Agreement Name

West Echols State Unit

8. Well No.  
1

9. Pool Name or Wildcat  
Wildcat Mississippian

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator  
Yates Petroleum Corporation

3. Address of Operator  
105 South 4th Str., Artesia, NM 88210

4. Well Location  
Unit Letter J : 1980 feet from the South line and 1980 feet from the East line  
Section 17 Township 11S Range 38E NMPM County Lea

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3904' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Propose to P&A well as follows:

- 1) TIH w/open-ended tubing and load hole w/9.5# mud laden fluid.
- 2) Set CIBP @ 6150' and dump 35' cement on plug.
- 3) Spot 50 sx plug 4841-4421'. WOC and tag.
- 4) Perforate 5-1/2" casing @ 2278' and place 100' cement plug inside 5-1/2" casing and in 5-1/2" x 8-5/8" annulus 2278-2178'.
- 5) Perforate 5-1/2" casing @ 445' and place 100' cement plug inside 5-1/2" casing and in 5-1/2" x 8-5/8" annulus 445-345'. WOC and tag.
- 6) Spot 10 sx plug @ surface.
- 7) Cut off head and weld on cap. Install dry-hole marker and clean location.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

Thereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stormi Davis TITLE Regulatory Compliance Technician DATE 5/5/03

Type or print name Stormi Davis Telephone No. 505-748-1471

(This space for State use) Hayden W. Wink OC FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY Hayden W. Wink DATE MAY 08 2003

Conditions of approval, if any: