

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-23541
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE
State Oil & Gas Lease No. 8055
Lease Name or Unit Agreement Name North Vacuum Abo Unit
Well No. 139
Pool name or Wildcat Vacuum; Abo, North

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Injector	
Name of Operator Mobil Producing TX & NM Inc.	
Address of Operator PO Box 4358 Houston, Texas 77210-4358	
Well Location Unit Letter L Feet From The South Line and 860 Feet From The West Line Section 14 Township 17-S Range 34-E NMPM Lea County	
Elevation (Show whether DF, RKB, RT, GR, etc.)	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-4-04 POH W/packer & RBP. Set 4 1/2" CIBP on tbq.

6-7-04 Notify NMICD @ 8:05 CST (Karen & Johnney) of plugs.
Circulate well w/ plugging mud.

Spot 25 sks of cement @ 8450'-8071'. PUH to 6040' Spot 25 sks @ 6040'-5662'. PUH to 4106' Spot 25 sks @ 4106' Tagged @ 3793'.
PUH to 2885' Spot 25 sks @ 2885'-2507'. Spot 45 sks @ 2079'. Tagged TOC @ 1742'

6-8-04 Spot 20 sks @ 139'-surface. POH w/ tbq. Mech cut 5 1/2 csg 5' BGL. Refill well w/ cement.

Cut off wellhead & anchors 3' BGL. Cap well. Install dry hole marker. Clean location

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE P & A Manager


DATE 06-14-04

TYPE OR PRINT NAME Jack Shelton

TELEPHONE NO. 432-523-5155

(This space for State Use)

APPROVED BY



OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUN 30 2004