New Mexico Oil Conservation Division, District I

Form 3160-5 (september 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR

1625 N. French Drive Hobbs, NM 28240

FORM APPROVED OMB No. 1004-0135 Expires: January 31, 2004

BUREAU OF LAND MANAGEMENT 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS LC 029410A Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well 8920003410 Oil Well Gas Well Other Injection Well 8. Well Name and No. 2. Name of Operator MCA Unit # 169 ConocoPhillips Co. 9. API Well No. 3a. Address 3b. Phone No. (include area code) 30-025-00755 10. Field and Pool, or Exploratory Area 4001 Penbrook, Odessa, TX 79762 505.676.5569 Maliamar, Grayburg - San Andres 4. Location of Well (Footage, Sec., T, R., M., or Survey Description) 1980' FSL & 660' FWL, Sec. 29, T 17S, R 32E, L 11. County or Parish, State Lea Co., NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Water Shut-Off Production (Start/Resume) Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Other Repair Pkr leak, Subsequent Report Change Plans Plug and Abandon Temporarily Abandon return to injection. Final Abandonment Notice Convert to Injection Plug Back Water Disposal Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 05/27/04 MIRU DDU - shutdown. 05/28/04 Held safety meeting - RU pump truck to kill well - ND wellhead, NU BOP - unset 4.5" X-1 pkr - POOH W/108 its of 2.375" tbg & lay down pkr - send pkr in for repairs - notified NMOCD of MIT test - shutdown. 06/01/04 Held safety meeting - bled well down, POOH W/kill string - PU redressed 4.5" X-1 pkr & RIH on 108 jts of 2.375" IPC tbg to 3,367 - test tbg to 5,000# psi below slips - all tbg tested good - circulated well W/60 bbls of pkr fluid - ND BOP, NU wellhead - test & run pressure chart on casing for 30 min @ 500# psi (Johnny Robinson NMOCD verbal approval) - casing tested good - clean location - RDMO. Chart enclosed

14. 1 hereby certify that the foregoing is true and correct Name (PrintedlTyped)

Kenneth N. Andersen

Title SHEaR Specialist

Signature

Date 06/21/04

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Name Approved by (Signature)

(Printed/Typed)

Office

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Date

GARY GOURLEY

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Continued on next page)



