

New Mexico Oil Conservation Division, District I
1625 N. French Drive
Hobbs, NM 88240

Form 3160-5
(September 2001)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

<p>1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other</p> <p>2. Name of Operator MARBOB ENERGY CORPORATION</p> <p>3a. Address PO BOX 227, ARTESIA, NM 88211-0227</p> <p>3b. Phone No. (include area code) (505) 748-3303</p> <p>4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1650 FNL 990 FEL, SEC. 6-T18S-R32E, UNIT H</p>	<p>5. Lease Serial No. NMNM90900</p> <p>6. If Indian, Allottee or Tribe Name</p> <p>7. If Unit or CA/Agreement, Name and/or No.</p> <p>8. Well Name and No. LUCKY LIZARD FEDERAL #1</p> <p>9. API Well No. 30-025-35886</p> <p>10. Field and Pool, or Exploratory Area NORTH YOUNG; WOLFCAMP</p> <p>11. County or Parish, State LEA CO., NM</p>
--	--

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input checked="" type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input checked="" type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

RECOMplete IN THE BONE SPRING AND/OR DELAWARE UNTIL COMMERCIAL PRODUCTION ESTABLISHED.

SET CIBP + 35' CMT @ 9800'. PERF THE BONE SPRING @ 9218-77' (10 SHOTS) & 8789-8814' (6 SHOTS). ACDZ @ 9218-77' W/ 2000 GAL NEFE 20% HCL. SWAB/FLOW TEST. ACDZ @ 8789-8814' W/ 1500 GAL NEFE 20% HCL. SWAB/FLOW TEST. PERF THE BONE SPRING @ 7976-84' (5 SHOTS), 7706-29' (6 SHOTS) & 7542-87' (9 SHOTS). ACDZ @ 7976-84' W/ 1000 GAL NEFE 20% HCL. SWAB/FLOW TEST. ACDZ @ 7706-29' W/ 2000 GAL NEFE 20% HCL. SWAB/FLOW TEST. ACDZ @ 7542-87' W/ 3000 GAL NEFE 20% HCL. SWAB/FLOW TEST. PERF THE BONE SPRING @ 7332-74' (6 SHOTS). ACDZ @ 7332-74' W/ 1500 GAL NEFE 20% HCL. SWAB/FLOW TEST. PERF THE BONE SPRING @ 5826-6028' (15 SHOTS). ACDZ @ 5826-6028' W/ 3000 GAL NEFE 20% HCL. SWAB/FLOW TEST. PERF THE DELAWARE @ 5336-54' (19 SHOTS). ACDZ @ 5336-54' W/ 1000 GAL NEFE 7.5% HCL. SWAB/FLOW TEST. IF DECISION MADE TO FRAC, WILL FRAC W/ 40K# SAND. PERF THE DELAWARE @ 5198-5220' (23 SHOTS). ACDZ @ 5198-5220' W/ 1250 GAL NEFE 7.5% HCL. SWAB/FLOW TEST. IF DECISION MADE TO FRAC, WILL FRAC W/ 40K# SAND. PERF THE DELAWARE @ 4438-46' (18 SHOTS). ACDZ @ 4438-46' W/ 500 GAL NEFE 7.5% HCL. SWAB/FLOW TEST. IF DECISION MADE TO FRAC, WILL FRAC W/ 20K# SAND.

14. I hereby certify that the foregoing is true and correct.
Name (Printed/Typed)

DIANA J. CANNON

Title **PRODUCTION ANALYST**

Signature

Date **JUNE 22, 2004**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by **APPROVED FOR 3 MONTH PERIOD**

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in subject lease which would entitle the applicant to conduct operations thereon.

Office

GARY GOURLEY
PETROLEUM ENGINEER

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

R2