

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-36529

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Cooper 8 (formally Laughlin 8)

8. Well Number
002

9. OGRID Number
023230

10. Pool name or Wildcat (DHC)
Monument; Tubb

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Tom Brown, Inc.

3. Address of Operator
P O Box 2608, Midland, TX 79702

4. Well Location
Unit Letter H : 1850 feet from the North line and 630 feet from the East line
Section 8 Township 20S Range 37E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3550 GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Completion ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached Completion detail

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Diane Kuykendall TITLE Operations Asst / Tech DATE 6/01/04

Type or print name Diane Kuykendall E-mail address: dkuykendall@tombrown.com Telephone No. 432-688-9773

(This space for State use)

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER DATE JUL 13 2004
Conditions of approval, if any:

Tom Brown, Inc.

Cooper 8 #2

API #30-025-36529

Sec 8, T20S, R37E

Lea County, NM

3/08/04 MIRU PU. Perf Abo from 7088-7092 & 6992-7002 w/ 3 SPF

3/09/04 RIH w/ tbg & pkr. Set pkr @ 6890.

3/11/04 Acidize Abo 6992-7092 w/ 2500 gals 15% HCL NEFE. Swab well

3/12/04 POOH w/ tbg & pkr. Set CIBP @ 6952, dump 30' cmt on top. PBTD @ 6922. Perf Drinkard from 6694-6714 w/ 2 SPF. RIH w/ tbg & pkr.

3/13/04 Set pkr @ 6721. Acidize Drinkard 6694-6714 w/ 3000 gals 15% HCL NEFE. Swab well

3/17/04 POOH w/ tbg & pkr. RIH w/ 5-1/2" 17# PSTH 10K RBP, set RBP @ 6640. Perf Tubb from 6518-6528 w/ 6 SPF. RIH w/ tbg & pkr.

3/18/04 Set pkr @ 6388. Spot 1000 gals 15% HCL NEFE acid over Tubb perfs 6518-6528. Re-set pkr @ 6357

3/19/04 Swab well. POOH w/ tbg & pkr. ND BOP, NU frac valve. SI waiting on frac job.

4/02/04 Pump w/ 3500 gals 15% HCL NEFE acid (Tubb perf 6518-6528) ahead of sand frac. Sand Frac w/ 195,200 lbs 20/40 white sand. Open well to tank

4/08/04 RIH w/ tbg & pkr. Set pkr @ 6427. ND BOP, NU 5K tree. RU Swab. Swab well

4/15/04 POOH w/ tbg & pkr. Release RBP @ 6640. RIH w/ pkr and set @ 6640. Swab well

4/17/04 Release pkr and POOH w/ tbg & pkr. RIH w/ tbg

4/20/04 RIH w/ pump and rods. NU WH, install rental test pumping equipment

4/26/04 Turn well to test equipment.

5/06/04 MIRU. POH w/ rods & pump

5/07/04 RIH w/ RBP. Set RBP @ 6633 and Pkr @ 6612. Test pressure. Held good. POH w/ pkr & tbg. RIH w/ tbg. RIH w/ rods & pump.

5/08/04 Turn well to production

