State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE	OIL CONSERVATION DIVISION						1011000 1 1 0		
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St. Santa Fe, NM 87505				WELL A	WELL API NO. 30-025-29195			
DISTRICT II	January, 11112 07000				5. Indica	5. Indicate Type of Lease			
811 S. 1st Street, Artesia, NM 88210					FED			X	
DISTRICT III					6. State (Oil & Gas Lease No).		
1000 Rio Brazos Rd, Aztec, NM 87410									
SUNDRY NOTICES AND REPORTS ON WELLS									
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					7. Lease	7. Lease Name or Unit Agreement Name			
(FORM C-101 FOR SUCH PROPOSALS.)						NORTH HOBBS (G/SA) UNIT			
Type of Well:						1			
Oil Well	Gas Well Other INJECTOR					Section 19			
2. Name of Operator	T3					8. Well No. 332			
Occidental Permian, Ltd. 3. Address of Operator						ame or Wildcat	HOBBS (0	3/S A)	
1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200						and or writedar	HODBS (C	JISK)	
4. Well Location									
Unit Letter J : 1430	Feet From The	SOUTH	Line and	2535	Feet From The	EAST	Line		
Section 19	Township	18S		Range	38E	NMPM	LEA C	ounty	
	10. Elevation (Sha 3655 'GL	ow whether DF, R	KB, RT GR, e	etc.)					
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data									
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:									
PERFORM REMEDIAL WORK	PLUG AND ABAN	DON 🔲	REMEDIA	AL WORK	[X ALTERI	NG CASING		
TEMPORARILY ABANDON	CHANGE PLANS		COMME	NCE DRILLIN	IG OPNS.	PLUG 8	ABANDONMEN	NT F	
PULL OR ALTER CASING			CASING	TEST AND C	EMENT JOB	_		<u></u>	
OTHER:			OTHER:						
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.									
1. Pull injection equipment.									
2. Perforate San Andres Zone 1, 4062-66, 4100-06, and 4160-64. 2 JSPF, 180 deg ph. (34 holes).									
 Stimulate perfs 4134 – 4232 w/1600 g 15% NEFE HCL acid. RIH w/7" Guib UNI VI pc pkr, XL on/off tool w/1.875 ss "F" nipple. 									
5. 129 jts 2-7/8" Duoline tbg. Pkr set @4031 '.									
6. Circ csg w/165 bbl pkr fluid. Test csg to 600 psi for 30 min and chart for the NMOCD.									
7. NU Wellhead. RDPU. Clean Location. Rig up Date: 07/08/2004								90.0	
						13	Hobbs	. ,	
Rig up Date: 07/08/2004						\ \ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	OCD		
Rig Down Date: 07/10/2004						1200			
						16	(seveni)	/	
I hereby certify that the information above is tr	rue and complete to the	e best of my know	ledge and be	lief.				·-	
SIGNATURE PLIF	4.11 +	,	TITLE			 = -			
1000 7	-ww		_ IIILE	Workove	er Compl Spec		0772172		
TYPE OR PRINT NAME Robert Gilb	pert					TELEPHONE N	O. 505/397-8	3206	
APPROVED BY HOUSE OCHEED REPRESENTATIVE II/STAFF MANAGER DATE									
APPROVED BY	· Will	2	JC HMFD	KELKEGEI	AIV. 11.1 1.1.0	DA	TE JUL 2	P/ 0000	
CONDITIONS OF APPROVAL IF ANY:							JOL Z	2004	

