## State of New Mexico Energy, Minerals and Natural Resources Department

FILE IN TRIPLICATE

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE	OIL CONSERVATION DIVISION							1001304 1-1-6	0,7
DISTRICT I	2040 Pacheco St. Santa Fe, NM 87505					WELL API N	O.		
P.O. Box 1980, Hobbs, NM 88240						30-025-28886			
DISTRICT II						5. Indicate Ty	pe of Lease		
811 S. 1st Street, Artesia, NM 88210						FED	STATE	X FE	E
DISTRICT III						6. State Oil &	Gas Lease No.	· · · · · · · · · · · · · · · · · · ·	
1000 Rio Brazos Rd, Aztec, NM 87410									
SUNDRY NOTICES AND REPORTS ON WELLS									
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						7. Lease Name or Unit Agreement Name			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)						NORTH HOBBS (G/SA) UNIT			
1. Type of Well:	ORAL C-101 FOR SUCH FROFUSALS.)					NORTH HO	JBBS (G/SA)	UNII	
Oil Well X	Gas Well	Other							
2. Name of Operator						8. Well No.	242		
Occidental Permian Ltd.									
3. Address of Operator						9. Pool name	or Wildcat	HOBBS (	G/SA)
1017 W. Stanolind Rd., HOBBS, 4. Well Location	NM 88240	505/39	7-8200						
Unit Letter N : 200	Feet From The	SOUTH		1400	Feet	From The	WEST	Line	
Section 30	Township	18S		Range	38E	NM	DΜ	IDA C	County
	10. Elevation (Show		B, RT GR, et		36E	11171	VIIIIIIIIII	LEA C	ounty
	3650 GL			,					
11. Chec	k Appropriate Box to	Indicate Na	ture of No	tice, Report	t, or Ot	her Data	<u> </u>		
NOTICE OF INT	ENTION TO:						REPORT OF	:	
PERFORM REMEDIAL WORK	PLUG AND ABANDO	ом 🗀	REMEDIA	AL WORK			ALTERING		Γ
TEMPORARILY ABANDON	CHANGE PLANS					, 님			
PULL OR ALTER CASING	OHANGE I LANG		l	ICE DRILLIN			PLUG & AI	BANDONMEI	NT
			CASING	TEST AND C	EMENT	JOB	j		
OTHER: Production Test TA'd pro		X	OTHER:						
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.									
1 DO 1 - 4 4200									
<ol> <li>DO plugs to ±4300.</li> <li>Acidize perfs.</li> </ol>									
3. Run production equipment.									
4. Temporarily production test to ta	nks.						10171	0000	•
,, p							1276	3192077	200
							,6		* * **
							/2/2	OCD	
							12.13.74	Hobbs	
							E	JEV. JOHN	4
							14.	FOR BUA	À
							/%	Table Cité	ز ز
							100	<b>V</b>	/
11 1 25 11 1							150	Chamte	~ \@\\
I hereby certify that the information above is to	us and complete to the bes	st of my knowled	ge and belief	:				V & C V	
SIGNATURE SIGNATURE	1		TITLE	Engineerin	ıo Advis	sor	DATE	7-26	-04
TYPE OR PRINT NAME D. NELSON			-	Zugmeern	15 / 10 / 1.		LEPHONE NO.		
(This space for State Use)						16	LLI HONE NO.	505/397-8	3200
APPROVED BY								uo o 1	0001
	WWW.		CUFFED	REPRESEN	NTATI	VE II/ST <b>AFI</b>	MANAGE	U <u>b 04</u>	2004
CONDITIONS OF APPROVAL IF ANY:									