Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	March 4, 2004 WELL API NO. 30-025-10225
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name THOMAS LONG
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	THOMAS LONG
1. Type of Well:	8. Well Number 4
Oil Well Gas Well Other	
2. Name of Operator JOHN H. HENDRIX CORPORATION	9. OGRID Number 012024
3. Address of Operator P.O. BOX 3040, MIDLAND, TEXAS 79702-3040	10. Pool name or Wildcat DRINKARD
4. Well Location	
Unit Letter L: 1650 feet from the SOUTH line and 990 feet from the WEST line	
Section 11 Township 22S Range 37E	NMPM LEA County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
23368.5' RT Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Ptt Location: UL Sect Twp Rng Pit type Depth to Groundwater	
Distance from nearest surface water Below-grade Tank Location UL Sect Tw	pRng;
feet from theline andfeet from theline	2031-12
12 Charle Associate Provide Pr	
12 Charle Appropriate Pourte Indicate Nature of Nation	Part (S)
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: SUF	Report of Other Data
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SEQUENT REMORT OF: %
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ILLING ORNS PLUG AND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ILLING OPNS. PLUG AND ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A	ILLING OPNS. PLUG AND ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER: OTHER:	ILLING ORNS. PLUG AND MAD ABANDONMENT PLUG AND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER:	ABANDONMENT ABAND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: A	ABANDONMENT ABAND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1.) 06/11/04 - SET CEMENT RETAINER AT 4550'; SQUEEZED UNDER RETAINER SQUEEZE TO 750 PSI - O.K. 2.) 06/14/04 - SPOT 25 SX ON TOP OF CR.	ABANDONMENT ABAND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1.) 06/11/04 - SET CEMENT RETAINER AT 4550'; SQUEEZED UNDER RETAINER SQUEEZE TO 750 PSI - O.K. 2.) 06/14/04 - SPOT 25 SX ON TOP OF CR. 3.) 06/15/04 - CUT 5 ½" CASING AT 3018'; POOH WITH 5 ½".	ABANDONMENT ND ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion WITH 200 SX CMT; PRESSURE TEST
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1.) 06/11/04 - SET CEMENT RETAINER AT 4550'; SQUEEZED UNDER RETAINER SQUEEZE TO 750 PSI - O.K. 2.) 06/14/04 - SPOT 25 SX ON TOP OF CR. 3.) 06/15/04 - CUT 5 ½" CASING AT 3018'; POOH WITH 5 ½". 4.) 06/16/04 - DUE TO BUDDY HILL WITH THE OCD, RIH TO 3072' (72' INSIDE COMOC; RIH AND TAGGED TOC AT 2607'. (CONT. ON BACK)	ASING STUB) AND PUMPED 200 SX CMT;
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1.) 06/11/04 - SET CEMENT RETAINER AT 4550'; SQUEEZED UNDER RETAINER SQUEEZE TO 750 PSI - O.K. 2.) 06/14/04 - SPOT 25 SX ON TOP OF CR. 3.) 06/15/04 - CUT 5 ½" CASING AT 3018'; POOH WITH 5 ½". 4.) 06/16/04 - DUE TO BUDDY HILL WITH THE OCD, RIH TO 3072' (72' INSIDE COMOC; RIH AND TAGGED TOC AT 2607'. (CONT. ON BACK) I hereby certify that the information above is true and complete to the best of my knowledge to the post of my	ASING STUB) AND PUMPED 200 SX CMT;
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1.) 06/11/04 - SET CEMENT RETAINER AT 4550'; SQUEEZED UNDER RETAINER SQUEEZE TO 750 PSI - O.K. 2.) 06/14/04 - SPOT 25 SX ON TOP OF CR. 3.) 06/15/04 - CUT 5 ½" CASING AT 3018'; POOH WITH 5 ½". 4.) 06/16/04 - DUE TO BUDDY HILL WITH THE OCD, RIH TO 3072' (72' INSIDE COMOC; RIH AND TAGGED TOC AT 2607'. (CONT. ON BACK)	ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ND ABA
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DR PULL OR ALTER CASING □ MULTIPLE □ CASING TEST A COMPLETION CEMENT JOB OTHER: □ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1.) 06/11/04 - SET CEMENT RETAINER AT 4550'; SQUEEZED UNDER RETAINER SQUEEZE TO 750 PSI - O.K. 2.) 06/14/04 - SPOT 25 SX ON TOP OF CR. 3.) 06/15/04 - CUT 5 ½" CASING AT 3018'; POOH WITH 5 ½". 4.) 06/16/04 - DUE TO BUDDY HILL WITH THE OCD, RIH TO 3072' (72' INSIDE COMPOC; RIH AND TAGGED TOC AT 2607'. (CONT. ON BACK) I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines ☑, a general permit □ SIGNATURE □ TITLE AGENT	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ND AB
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DR PULL OR ALTER CASING □ MULTIPLE □ CASING TEST A COMPLETION CEMENT JOB OTHER: □ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1.) 06/11/04 - SET CEMENT RETAINER AT 4550'; SQUEEZED UNDER RETAINER SQUEEZE TO 750 PSI - O.K. 2.) 06/14/04 - SPOT 25 SX ON TOP OF CR. 3.) 06/15/04 - CUT 5 ½" CASING AT 3018'; POOH WITH 5 ½". 4.) 06/16/04 - DUE TO BUDDY HILL WITH THE OCD, RIH TO 3072' (72' INSIDE C WOC; RIH AND TAGGED TOC AT 2607'. (CONT. ON BACK) I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit □ SIGNATURE □ TITLE AGENT Type or print name HOWARD BOATRIGHT E-mail address: CGIBSON@TETRAT	ASING STUB) AND PUMPED 200 SX CMT; e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 06/29/2004 EC.COM Telephone No. (432)685-3447
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DR PULL OR ALTER CASING □ MULTIPLE □ CASING TEST A COMPLETION CEMENT JOB OTHER: □ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1.) 06/11/04 - SET CEMENT RETAINER AT 4550'; SQUEEZED UNDER RETAINER SQUEEZE TO 750 PSI - O.K. 2.) 06/14/04 - SPOT 25 SX ON TOP OF CR. 3.) 06/15/04 - CUT 5 ½" CASING AT 3018'; POOH WITH 5 ½". 4.) 06/16/04 - DUE TO BUDDY HILL WITH THE OCD, RIH TO 3072' (72' INSIDE C WOC; RIH AND TAGGED TOC AT 2607'. (CONT. ON BACK) I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit □ SIGNATURE □ TITLE AGENT Type or print name HOWARD BOATRIGHT E-mail address: CGIBSON@TETRAT	ASING STUB) AND PUMPED 200 SX CMT; e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 06/29/2004 EC.COM Telephone No. (432)685-3447
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DR PULL OR ALTER CASING □ MULTIPLE □ CASING TEST A CEMENT JOB OTHER: □ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1.) 06/11/04 - SET CEMENT RETAINER AT 4550'; SQUEEZED UNDER RETAINER SQUEEZE TO 750 PSI - O.K. 2.) 06/14/04 - SPOT 25 SX ON TOP OF CR. 3.) 06/15/04 - CUT 5 ½" CASING AT 3018'; POOH WITH 5 ½". 4.) 06/16/04 - DUE TO BUDDY HILL WITH THE OCD, RIH TO 3072' (72' INSIDE COMOC; RIH AND TAGGED TOC AT 2607'. (CONT. ON BACK) I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been will be constructed or closed according to NMOCD guidelines ☑, a general permit □ SIGNATURE □ TITLE AGENT Type or print name HOWARD BOATRIGHT E-mail address: CGIBSON@TETRAT	ASING STUB) AND PUMPED 200 SX CMT; e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 06/29/2004 EC.COM Telephone No. (432)685-3447

- 5.) 6/16/04 SPOT 100 SX AT 1100'
- 6.) 6/17/04 PERFERATED 8 5/8" CASING AT 325'. PUMPED 230 SX. FILLED WELL WITH CEMENT TO SURFACE FROM 8 5/8 13 3/8 ANNULUS, AND INSIDE 8 5/8
- 7.) CUT OFF WELL HEAD.