Form 3160-5 (August 1999) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000 5. Lease Serial No. NMNM90900 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well 🔲 Gas Well 📋 Oth			8. Well Name and No. LUCKY LIZARD FED 01				
2. Name of Operator MARBOB ENERGY CORPOR	ION lion@marbob.com	9. API Well No. 30-025-35886-00-S2					
3a. Address 3b. Phone I P. O. BOX 227 Ph: 505.7 ARTESIA, NM 88211-0227 Fx: 505.7					10. Field and Pool, or Exploratory UNDESIGNATED		
4. Location of Well (Footage, Sec., T	11. County or Parish, and State			and State			
Sec 6 T18S R32E SENE 1650		LEA COUNTY, NM					
12. СҢЕСК АРРИ	ROPRIATE BOX(ES) T	O INDICATE	NATURE OF 1	NOTICE, R	LEPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
□ Notice of Intent	ntent Acidize		Deepen P		roduction (Start/Restine)2820 Water Shut-Off		
Subsequent Report	Alter Casing	-	ture Treat	C Reclan	1 A.V	U Well Integrity	
	Casing Repair	□ New Construction □ R			ipleten.	, y Other ha	
Final Abandonment Notice	 Change Plans Convert to Injection 	ange Plans Plug and Abandon Novert to Injection Plug Back V			mporantiy Abandon (2) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1		
determined that the site is ready for f TESTED THE BONE SPRING SET CIBP @ 9820' & DUMP @ 9218-77' W/ 2000 GAL NE OR GAS. SET CIBP @ 8750'. ACDZ @ 7976-84' W/ 1000 G NEFE 20%. SWAB, NON-CO OIL OR GAS. PERF @ 7332- SET CIBP @ 7232'. PERF @ HCL. SWAB. REC 1000' FLU 16/30 PROPPANT. NO OIL C 5336-54' (19). DUMP CMT OI DUMP CMT ON CIBP. PUMP	A, DELAWARE AND QUE 35' CMT ON TOP. PERF FE 20%. SWAB, NO OIL PERF @ 7976-84' (5), 7 AL 20% NEFE HCL. SW MMERCIAL OIL & GAS S 74' (6). ACDZ @ 7332-74 5826-6028' (15). DUMP ID PER HR W/ 15% OIL PER HR W/ 15% OIL N GIAS SHOW, ONLY B N CIBP. SWAB, NO SHO	THE BONE S OR GAS SH 7706-29 (6) & AB, NO OIL (SHOWS. ACE 4' W/ 1500 GA CMT ON CIB CUT & GAS. LACK WATEF WO OIL OR GA	Spring @ 9218 DW. Straddle 7542-87' (9). DL DR GAS SHOW. IZ @ 7542-87' V L NEFE 20%. S P. ACDZ @ 5826 FRAC @ 5826-6 R. SET CIBP @ AS. SET CIBP @	E @ 8789-8 JMP 35' CM ACDZ @ 7 V/ 3000 GA WAB, NO (6-6028' W/ 6028' DOW! 5750'. PER \$ 5300'. PER	814', SWAB, NO SH IT ON CIBP. 7706-26' W/ 2000 GA L NEFE 20%. SWAB OIL OR GAS SHOW. 3000 GAL NEFE 20' N 5 1/2" CSG W/ 100 IF THE DELAWARE RF @ 4438-46' (18).	OW OIL , NO SHOW % K# @	
14. I hereby certify that the foregoing is	Electronic Submission	#34387 verified	by the BLM We	II Informatio	n System	<u> </u>	
For MARBOB ENERGY CORP Committed to AFMSS for processing by LI Name(Printed/Typed) DIANA CANNON			ORATION, sent to the Hobbs NDA ASKWIG on 08/10/2004 (04LA0295SE) Title REGULATORY TECH- PRODUCTION				
Signature (Electronic S	Submission) THIS SPACE F	OR FEDERA	Date 08/10/2		JSE		
			DAVID R GLASS				
_Approved By_ACCEPTED					NEER	Date 08/11/20	
Conditions of approval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to cond	Office Hobbs						
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent					make to any department or	r agency of the United	
	ISED ** BLM REVISE	D ** BLM R	EVISED ** BLI	M REVISE	D ** BLM REVISE	D **	

Additional data for EC transaction #34387 that would not fit on the form

32. Additional remarks, continued

@ 3654-65' (24). DUMP 35' CMT ON CIBP. SWAB. ACDZ @ 3654-65' W/ 1000 GAL NEFE 7.5% HCL. SWAB, NO OIL OR GAS SHOW.