Office	lew Mexico	Form C-103
District I Energy, Minerals and Natural Resources		March 4, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II	A TION I DIVIGIONI	30-025-35748
1501 111 01410 111 01,111 00210	ATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd. Aztec. NM 87410	St. Francis Dr.	STATE X FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	NM 87505	6. State Oil & Gas Lease No.
87505		VO 6364
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name North Lusk 32 State
PROPOSALS.) 1. Type of Well:		8. Well Number
Oil Well X Gas Well Other		1
2. Name of Operator		9. OGRID Number 227001
Latigo Petroleum Inc		227001
3. Address of Operator 415 W. Wall, Suite 1900		10. Pool name or Wildcat
Wildiand, 1X 79701		Lusk Strawn
4. Well Location		
Unit Letter L: 1980 feet from the S line and 660 feet from the W line		
Section 32 Township 18S Range 32E NMPM County LEA		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3691' Gr		
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)		
Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well		
Distance from nearest surface water Below-grade Tank Location ULSectTwpRng;		
feet from theline andfeet from theline		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □		
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRI	LLING OPNS. PLUG AND
PULL OR ALTER CASING	CASING TEST AN CEMENT JOB	ABANDONMENT ND
OTHER: Stimulate Strawn perf & add WC perfs	OTHER:	\boxtimes
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Stimulate Strawn perfs 11,632'-11,642' Set CIBP @ 11,362' w/2 sx cmt, perf Wolfcamp 10,492'-10,508' 68 holes, acidize, swab, return to producing		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-		
grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD approved plan.		
SIGNATURE DIMNU Squalland TITLE Production Analyst DATE 07/26/2004		
Type or print name Bonnie Husband	-mail address: bhusband@la	tigopetro.com Telephone No.(432)684-4293
(This space for State use)		
APPPROVED BY Conditions of approval, if any: DATE AUG 1 2 2004		
Conditions of approval, if any:		