

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-02312
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-7990
7. Lease Name or Unit Agreement Name Central EK Queen Unit
8. Well Number 002
9. OGRID Number 020497
10. Pool name or Wildcat EK Yates - Seven Rivers - Queen

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other ☐ Water Injection Well ☐

2. Name of Operator
Seely Oil Company

3. Address of Operator
815 W. 10th St., Ft. Worth, TX 76102

4. Well Location
Unit Letter P: 660 feet from the South line and 660 feet from the East line
Section 8 Township 18S Range 34E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4070' DF

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL _____ Sect _____ Twp _____ Rng _____ Pit type STEEL Depth to Groundwater 148' Distance from nearest fresh water well N/A

Distance from nearest surface water N/A Below-grade Tank Location UL _____ Sect _____ Twp _____ Rng _____ ; OVER 1000'

feet from the _____ line and _____ feet from the _____ line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
- TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
- PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
- OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
- COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
- CASING TEST AND CEMENT JOB ☐
- OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. CIBP @ 4350' w/ 35' cmt on top
2. 25 sxs @ 3100'
3. 25 sxs @ 1700' (tag plug) — PERF 4 HOLES @ 5025 SXS
4. Perf 4 holes @ 423'

5. Pump 50 sxs half in / half out
6. Erect dry hole marker & clean location
THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE David L. Henderson

TITLE: Executive Vice President

DATE: 8/26/04

Type or print name: David L. Henderson

E-mail address: dhenderson@seelyoil.com

Telephone No.: 817-332-1377

(This space for State use)

APPROVED BY Buyer's Clerk

TITLE OG FIELD REPRESENTATIVE II/STAFF MANAGER DATE AUG 31 2004

Seely Oil Company
Central EK Queen Unit No. 002
660' FSL & 660' FEL Sec. 8-T13S-R34E
Lea County New Mexico

