

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-32763

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
BALMS
Plants 23 State

8. Well Number 1

9. OGRID Number
013300

10. Pool name or Wildcat
Eumont-Yates-7 Rivers-Queen

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
Lewis B. Burleson, Inc.

3. Address of Operator
P.O. Box 2479 Midland, Texas 79702

4. Well Location
Unit Letter A : 990 feet from the North line and 660 feet from the East line
Section 20 Township 19-S Range 37-E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3659 GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type ☒ Depth to Groundwater 48 Distance from nearest fresh water well 2600' Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:


REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) Set CIBP at 3100' with 25 sacks cement cap
- 2) Circulate 5-1/2" casing with mud laden fluid
- 3) Set 25 sacks cement 2700-2600
- 4) Set 25 sacks cement 1200-1100 WOC and tag
- 5) Set 25 sacks cement 450-350 WOC and tag
- 6) Set surface plug
- 7) Install marker

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Wayne Jarvis TITLE Production Supt. DATE 8/26/2004

Type or print name Wayne Jarvis
For State Use Only

E-mail address: GEOTTECH@Prodigy. Telephone No. 432/683-4747
Net

APPROVED BY: Chris Williams TITLE DISTRICT SUPERVISOR/GENERAL MANAGER
Conditions of Approval (if any):

SEP 01 2004