Submit 3 Copies To Appropriate District	State of No		Form C-103 March 4, 2004
District I 1625 N. French Dr., Hobbs, NM 88240	French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	CT II OIL CONSERVATION DIVISION OIL CONSERVATION DIVISION		30 025 09211
District III	trict III 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe.	NM 87505	6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	,	- 1	014904
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			J. F. Janda N.T. "1"
PROPOSALS.)		,	8. Well Number
1. Type of Well:			2
Oil Well Gas Well	Other		
2. Name of Operator			9. OGRID Number
		······	000962
3. Address of Operator	2700		10. Pool name or Wildcat
P O Box 10340, Midland, Texas 79	9702		Jalmat
4. Well Location			
Unit LetterD:	990feet from the	_north line and	990feet from the _westline
Section 2		S Range 36E	
	11. Elevation (Show whe 3484' GR	ther DR, RKB, RT, GF	R, etc.)
Pit or Below-grade Tank Application (For	r pit or below-grade tank closur	es, a form C-144 must be a	ittached)
Pit Location: ULSectTwp_	Rng Pit type	Depth to Groundy	vaterDistance from nearest fresh water well
Distance from nearest surface water	Below-grade Tank Loca	tion ULSect	TwpRng;
			l de la companya de
feet from the line and	feet from the	line	
	Appropriate Box to Ind	licate Nature of No	tice, Report or Other Data SUBSEQUENT REPORT OF: WORK ALTERING CASING
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK	Appropriate Box to Ind	licate Nature of No	SUBSEQUENT REPORT OF: WORK
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK	Appropriate Box to Ind ITENTION TO: PLUG AND ABANDON	licate Nature of No	SUBSEQUENT REPORT OF: WORK
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	Appropriate Box to Ind ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE	licate Nature of No	SUBSEQUENT REPORT OF: WORK
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	Appropriate Box to Ind ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	licate Nature of No REMEDIAL COMMENC CASING TE CEMENT J OTHER:	SUBSEQUENT REPORT OF: WORK
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compof starting any proposed wor recompletion. 1. TAG CIBP @ 2952'; SPOTTED 2. PERF @ 1700'; PMP 30 SX CM 3. TAG PLUG @ 1540'. 4. PERF @ 365'; CIRC TO SURFA	Appropriate Box to Ind ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly ork). SEE RULE 1103. For	REMEDIAL COMMENCE CASING TE CEMENT J OTHER: state all pertinent deta or Multiple Completion Approv	SUBSEQUENT REPORT OF: WORK
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compof starting any proposed wor recompletion. 1. TAG CIBP @ 2952'; SPOTTED 2. PERF @ 1700'; PMP 30 SX CM 3. TAG PLUG @ 1540'.	Appropriate Box to Ind ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly ork). SEE RULE 1103. For	REMEDIAL COMMENCE CASING TE CEMENT J OTHER: state all pertinent deta or Multiple Completion Approv	SUBSEQUENT REPORT OF: WORK ALTERING CASING ALTERING ALTER
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compof starting any proposed wor recompletion. 1. TAG CIBP @ 2952'; SPOTTED 2. PERF @ 1700'; PMP 30 SX CM 3. TAG PLUG @ 1540'. 4. PERF @ 365'; CIRC TO SURFA 5. INSTALL P&A MARKER. I hereby certify that the information	Appropriate Box to IndITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detected operations. (Clearly ork). SEE RULE 1103. For 25 SX CMT @ 2712'-295 TT. ACE 12 SX.	Ilicate Nature of No REMEDIAL COMMENC CASING TE CEMENT J OTHER: state all pertinent deta or Multiple Completion 2' Approv Liability surface	SUBSEQUENT REPORT OF: WORK ALTERING CASING ALTERING ALTER
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compof starting any proposed wor recompletion. 1. TAG CIBP @ 2952'; SPOTTED 2. PERF @ 1700'; PMP 30 SX CM 3. TAG PLUG @ 1540'. 4. PERF @ 365'; CIRC TO SURFA 5. INSTALL P&A MARKER. I hereby certify that the information	Appropriate Box to IndITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Pleted operations. (Clearly ork). SEE RULE 1103. For 25 SX CMT @ 2712'-295 TT. ACE 12 SX. Above is true and complete a closed according to NMOCD grant accordi	Ilicate Nature of No REMEDIAL COMMENC CASING TE CEMENT J OTHER: state all pertinent deta or Multiple Completion 2' Approv Liability surface	SUBSEQUENT REPORT OF: WORK ALTERING CASING ALT
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compostarting any proposed we or recompletion. 1. TAG CIBP @ 2952'; SPOTTED 2. PERF @ 1700'; PMP 30 SX CM 3. TAG PLUG @ 1540'. 4. PERF @ 365'; CIRC TO SURFA 5. INSTALL P&A MARKER. I hereby certify that the information grade tank has been/will be constructed or	Appropriate Box to IndITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly ork). SEE RULE 1103. For 25 SX CMT @ 2712'-295 TT. ACE 12 SX. above is true and complete a closed according to NMOCD gray.	REMEDIAL COMMENCE CASING TE CEMENT J OTHER: state all pertinent deta or Multiple Completion Approv Liability surface e to the best of my know guidelines , a general per	SUBSEQUENT REPORT OF: WORK
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composition of starting any proposed woor recompletion. 1. TAG CIBP @ 2952'; SPOTTED 2. PERF @ 1700'; PMP 30 SX CM 3. TAG PLUG @ 1540'. 4. PERF @ 365'; CIRC TO SURF 5. INSTALL P&A MARKER. I hereby certify that the information grade tank has been/will be constructed on SIGNATURE Type or print name TOMMY TA' (This space for State use)	Appropriate Box to IndITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly ork). SEE RULE 1103. For 25 SX CMT @ 2712'-295 TT. ACE 12 SX. above is true and complete a closed according to NMOCD gray.	REMEDIAL COMMENCE CASING TE CEMENT J OTHER: state all pertinent deta or Multiple Completion Z' Approv Liability surface e to the best of my knot guidelines \(\), a general per TITLE AGENT mail address: ttaylor@	SUBSEQUENT REPORT OF: WORK
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composition of starting any proposed wor recompletion. 1. TAG CIBP @ 2952'; SPOTTED 2. PERF @ 1700'; PMP 30 SX CM 3. TAG PLUG @ 1540'. 4. PERF @ 365'; CIRC TO SURF 5. INSTALL P&A MARKER. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name TOMMY TA	Appropriate Box to IndITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly ork). SEE RULE 1103. For 25 SX CMT @ 2712'-295 TT. ACE 12 SX. above is true and complete a closed according to NMOCD gray.	REMEDIAL COMMENCE CASING TE CEMENT J OTHER: state all pertinent deta or Multiple Completion Z' Approv Liability surface e to the best of my knot guidelines \(\), a general per TITLE AGENT mail address: ttaylor@	SUBSEQUENT REPORT OF: WORK