

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
March 4, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-34879
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Shell State
8. Well Number 4
9. OGRID Number 017891
10. Pool name or Wildcat W. Red Tank Delaware

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator Pogo Producing Company	
3. Address of Operator P. O. Box 10340, Midland, TX 79702-7340	
4. Well Location Unit Letter <u>E</u> : <u>1650</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line Section <u>36</u> Township <u>22</u> Range <u>32</u> NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3749'	
<b>Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)</b>	
Pit Location: UL _____ Sect _____ Twp _____ Rng _____ Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Below-grade Tank Location UL _____ Sect _____ Twp _____ Rng _____ ; _____ feet from the _____ line and _____ feet from the _____ line	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/> Add Perfs <input checked="" type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Cathy Wright TITLE Sr. Engineering Tech DATE 08/31/04  
Type or print name Cathy Wright E-mail address: \_\_\_\_\_ Telephone No. 432-685-8100

(This space for State use)

APPROVED BY Chris Williams TITLE OC DISTRICT SUPERVISOR/GENERAL MANAGER DATE SEP 03 2004  
Conditions of approval, if any: \_\_\_\_\_

Pogo Producing Company  
Shell State #4  
E/36/T22S/R32E  
Lea County, NM  
30-025-34879

08/03/04 POOH w/ rods & pump. Set CIBP @ 8050. Perf sqz holes 6210 & 6212. Test CIBP to 3000# ok.  
08/04/04 Cmt thru sqz holes w/ 300 sks Cl "C" + add @ 14.1 ppg followed by 100 sks Cl "C" Neat @ 14.8 ppg.  
08/05/04 DO cmt.  
08/06/04 Perf Delaware 6192-6203, 6223-35, 6317-25 w/ 1 spf.  
08/07/04 Acdz w/ 1500 gals 7-1/2% acid. Swab.  
08/12/04 Frac w/ 19,500# 14/30 Liteprop followed by 3,375# 16/30 SLC. Swab.  
08/16/04 Return well to production.