Submit 3 copies to Appropriate District Office State of New Mexico Energy, Minerals and Natural Resources Department	Form C-103 Revised 1-1-89
OIL CONSERVATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	30-025-25818
Santa Fe, New Mayico 87504-2088	5. Indicate Type of Lease
P.O. Box Drawer DD, Artesia, NM 88210 DISTRICT III	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil / Gas Lease No. NM-1021
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.	7. Lease Name or Unit Agreement Name CENTRAL VACUUM UNIT
1. Type of Well: OIL ☐ GAS ☐ OTHER WATER INJECTION WELL	
Name of Operator CHEVRON USA INC	8. Well No. 46
3. Address of Operator 15 SMITH ROAD, MIDLAND, TX 79705	9. Pool Name or Wildcat VACUUM GRAYBURG SAN ANDRES
4. Well Location	VACOUN GIVE BONG SAIV ANDRES
Unit Letter A: 119 Feet From The NORTH Line and 1224	Feet From The <u>EAST</u> Line
Section 31 Township 17S Range 35E NN	IPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3976' GR	
11. Check Appropriate Box to Indicate Nature of Notice, Report,	or Other Data
	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	✓ ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPE	
PULL OR ALTER CASING CASING TEST AND CEMEN	
OTHER: OTHER:	FISH PKR, & CLEAN OUT
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent deproposed work) SEE RULE 1103. Hirumann Mirumann Mirumann	EN ENDED. R TURNED LOOSE. TAG FILL @ 4268. I. TIH W/TREATING PKR, SN, WS TO 4259. R T26. OPEN WELL TO FRAC. REL PKR @ RIDED TO 2081 & SPOT 1 SX SAND ON RBP @ R 1167-1198. TOC @ 1107. R ENDED TO 1164.
8-20-04: TAG PLUG @ 1195. PU TO 1193. WOC 2 1/2 HRS. DISPL W/30 BFW. MIXED CMT & PUMI OPEN TBG VALVE TO DISPL 2 BBLS FW. PRESS UP ON CMT SQZ TO 750#. SQZ 2 BBLS CMT IN HESITATION #2 PRESSURE CSG TO 1327# FOR 30 MINS. #3 PRESS CSG TO 1305#. 8-23-04: TIH W/BHA & 2 3/8" WS TO TAG CMT @ 782. DRILL CMT FR 782-1104. 322' CMT DRILLEI 8-24-04: START DRILLING CMT @ 1104-1277. FELL THRU TO 1329. TAG SAND @ 4225. WASH S/8-25-04: REL RBP @ 4225. TIH W/PKR & 2 3/8" TBG 4222.67'. CIRC 90 BBLS PKR FLUID. SET PKF 8-26-04: CHART & TEST TO 340# FOR 30 MINS. NO LOSS. (GOOD) (ORIGINAL CHART & COPY CRIG DOWN. FINAL REPORT	TO FORMATION. REV CIRC 20 BBLS FW. D OUT. FIRST 30' CMT SOFT. 812' HARD. AND OFF RBP. R @ 4259'.

	rue and complete to the best of my knowledge and belief.		
SIGNATURE SIGNATURE	Krusk Slake TITLE Regulatory Specialist	alist DATE 9/1/2004	
TYPE OR PRINT NAME	Denise Leake	Telephone No. 915-687-737	75
			_

(This space for State Use)

APPROVED CONDITIONS OF APPROVAL IF ANY:

(This space for State Use)

APPROVED CONDITIONS OF APPROVAL IF ANY:

OC FIELD REPRESENTATIVE II/STAFF MANAGER

SEP 2 2 2004

