Submit 3 Copies To Appropriate Distr Office		of New Mexico	Form C-103	
District I	Energy, Minera	ls and Natural Resources	May 27, 2004	
1625 N. French Dr., Hobbs, NM 8724			WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 882	Grand Ave., Artesia, NM 88210 III 1220 South St. Francis Dr.		<b>30-025-30163</b> 5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 874			STATE <b>x</b> FEE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM		·····, · · · · · · · · · · · · · · · ·	6. State Oil & Gas Lease No. LH 1840	
SUNDRY N	OTICES AND REPOR	TS ON WELLS	7. Lease Name or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Corbin State	
Type of Well: Oil Well 🕱 Gas Well 🗌 Other			8. Well Number	
2. Name of Operator EOG Resources Inc.		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	9. OGRID Number	
3. Address of Operator			10 Declarance or Wildest	
P.O. Box 2267 Midland	Terrag 79702		10. Pool name or Wildcat West Corbin (Delaware)	
4. Well Location	, ICAAS / 9/02		West Corbin (Deraware)	
Unit LetterF Section 16	Township	the North line and 185 Range 33E awww.hether DR, RKB, RT, GR,	NMPM County Lea	
		3887 GL		
Pit or Below-grade Tank Application	n 🗌 or Closure 🗖 🔤			
Pit type Depth to Ground	lwater Distance fro	m nearest fresh water well	Distance from nearest surface water	
Pit Liner Thickness:			ction Material	
		to Indicate Nature of Notic		
NOTICE OF PERFORM REMEDIAL WORK	INTENTION TO:		JBSEQUENT REPORT OF:	
NOTICE OF ERFORM REMEDIAL WORK	INTENTION TO:		JBSEQUENT REPORT OF: K	
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON	INTENTION TO:		JBSEQUENT REPORT OF: K	
NOTICE OF PERFORM REMEDIAL WORK EMPORARILY ABANDON PULL OR ALTER CASING	INTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE	IDON  IDON	JBSEQUENT REPORT OF: K	
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	INTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION	IDON I REMEDIAL WORK	JBSEQUENT REPORT OF: K ALTERING CASING [ LLING OPNS. ] PLUG AND ABANDONMENT ND ] ND ]	
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed w or recompletion.	INTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION Pleted operations. (Clearly rork). SEE RULE 1103.	IDON       SL         IDON       REMEDIAL WOR         COMMENCE DRI       COMMENCE DRI         CASING TEST AN CEMENT JOB       OTHER:         V state all pertinent details, and g       OTHER:         Y state all pertinent details, and g       For Multiple Completions: Attained         Ethe wellbore for evaluation       Complexity	JBSEQUENT REPORT OF: ALTERING CASING [ LLING OPNS. ND PLUG AND ABANDONMENT ND Sincluding Estimated date ABANDONMENT ND Sincluding Estimated date ND ND Sincluding Estimated date ND ND ND Sincluding Estimated date ND ND Sincluding Estimated date ND ND Sincluding Estimated date ND ND ND ND ND ND ND ND	
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed w or recompletion.	INTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION Pleted operations. (Clearly rork). SEE RULE 1103.	IDON       SL         IDON       REMEDIAL WOR         COMMENCE DRI       COMMENCE DRI         CASING TEST AN CEMENT JOB       OTHER:         V state all pertinent details, and g       OTHER:         Y state all pertinent details, and g       For Multiple Completions: Attained         Ethe wellbore for evaluation       Complexity	JBSEQUENT REPORT OF: ALTERING CASING [ LLING OPNS.   PLUG AND ABANDONMENT ND   ABANDONMENT Sive pertiment dates Sincluding Estimated date of ach wellbore diagram of proposed completion N Hobbs 0CD	
NOTICE OF PERFORM REMEDIAL WORK EMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed w or recompletion. EOG Resources request after discussion w/ of Set CICR @ +/- 6500 Pump 150 sx cement :	INTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION Pleted operations. (Clearly vork). SEE RULE 1103. Pleted operations to TA Gary Wink as follows into perfs from 6558	IDON  IDON	JBSEQUENT REPORT OF: ALTERING CASING [ LLING OPNS. ND PLUG AND ABANDONMENT ND Sincluding Estimated date ABANDONMENT ND Sincluding Estimated date ND Hobbs OCD Sincluding for possibilities	
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed w or recompletion. EOG Resources request after discussion w/ of Set CICR @ +/- 6500	INTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION Pleted operations. (Clearly vork). SEE RULE 1103. Pleted operations to TA Gary Wink as follows into perfs from 6558	IDON  IDON	JBSEQUENT REPORT OF: ALTERING CASING [ LLING OPNS.   PLUG AND ABANDONMENT ND   ABANDONMENT ND   A	
NOTICE OF ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed w or recompletion. EOG Resources request after discussion w/ of Set CICR @ +/- 6500 Pump 150 sx cement : Run MIT test for 30 hereby certify that the informat	INTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION Pleted operations. (Clearly rork). SEE RULE 1103. Pleted operations to TA Gary Wink as follows into perfs from 6558 min	IDON       SL         IDON       REMEDIAL WOR         COMMENCE DRI       COMMENCE DRI         CASING TEST AN CEMENT JOB       OTHER:         v state all pertinent details, and g       OTHER:         y state all pertinent details, and g       For Multiple Completions: Attained to the wellbore for evaluation:         ' to 6574'       '''	JBSEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ND TO TO TO TO TO TO TO TO TO TO	
NOTICE OF PERFORM REMEDIAL WORK PEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composed work of starting any proposed work or recompletion. EOG Resources request after discussion w/ of Set CICR @ +/- 6500 Pump 150 sx cement : Rum MIT test for 30 hereby certify that the informat rade tank has been/will b2/constructed	INTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION Pleted operations. (Clearly rork). SEE RULE 1103. Pleted operations to TA Gary Wink as follows into perfs from 6558 min tion above is true and correct or closed according to NMC	IDON       SL         IDON       REMEDIAL WOR         COMMENCE DRI       COMMENCE DRI         CASING TEST AN CEMENT JOB       OTHER:         v state all pertinent details, and g       OTHER:         y state all pertinent details, and g       For Multiple Completions: Attained         the wellbore for evaluation:       *         ' to 6574'       *         mplete to the best of my knowled       OCD guidelines         _ TITLE       Regular	JBSEQUENT REPORT OF: ALTERING CASING [ LLING OPNS.   PLUG AND ABANDONMENT ND   ABANDONMENT ND   A	
NOTICE OF PERFORM REMEDIAL WORK PEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composed wor recompletion. EOG Resources request after discussion w/ of Set CICR @ +/- 6500 Pump 150 sx cement : Rum MIT test for 30 hereby certify that the informat rade tank has been/will b2 constructed	INTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION Pleted operations. (Clearly rork). SEE RULE 1103. Pleted operations. (Clearly rork). SEE RULE 1103. SEE RULE 1103. Pleted operations to TA Gary Wink as follows into perfs from 6558 min tion above is true and com- er	IDON       SL         IDON       REMEDIAL WORK         COMMENCE DRI       COMMENCE DRI         CASING TEST AN CEMENT JOB       OTHER:         v state all pertment details, and g       OTHER:         y state all pertment details, and g       For Multiple Completions: Attained         the wellbore for evaluation:       *         ' to 6574'       mplete to the best of my knowled         DCD guidelines       , a general perm         TITLE       Regular         E-mail address:       *	JBSEQUENT REPORT OF: ALTERING CASING [ LLING OPNS.   PLUG AND ABANDONMENT ND   ABANDONMENT ND   A	
NOTICE OF PERFORM REMEDIAL WORK PEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed w or recompletion. EOG Resources request after discussion w/ of Set CICR @ +/- 6500 Pump 150 sx cement : Run MIT test for 30 hereby certify that the informat rade tank has been/will be constructed IGNATURE The Market Start Constructed	INTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION Pleted operations. (Clearly rork). SEE RULE 1103. Pleted operations. (Clearly rork). SEE RULE 1103. SEE RULE 1103. Pleted operations to TA Gary Wink as follows into perfs from 6558 min tion above is true and com- er	IDON       SL         IDON       REMEDIAL WOR         COMMENCE DRI       COMMENCE DRI         CASING TEST AN CEMENT JOB       OTHER:         v state all pertinent details, and g       OTHER:         y state all pertinent details, and g       For Multiple Completions: Attained         the wellbore for evaluation:       *         ' to 6574'       *         mplete to the best of my knowled       OCD guidelines         _ TITLE       Regular	JBSEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ND Sive pertiment dates Sincluding Estimated date ach wellbore diagram of proposed.completion Hobbs OCD or of future workover possibilities Size Siz	

APPROVED BY	4	au
Conditions of Ap	prova	l, if any:

· -··--