Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side.					NMNM13276	
					6. If Indian, Allottee or Tribe Name	
					7. If Unit or CA/Agreement, Name and/or No. NMNM91026	
1. Type of Well					8. Well Name and No. SINAGUA 18 F.C. 01	
Oil Well Gas Well Other 2. Name of Operator Contact: BEVERLY HATFIELD					9. API Well No.	
MERIT ENERGY COMPANY	.hatfield@meriter	@meritenergy.com 30-025-32402-00-S1				
13727 NOEL ROAD #500 P			(include area code 8.1630 Ext: 630 .1252		10. Field and Pool, or Exploratory QUAIL RIDGE	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State	
Sec 18 T20S R34E SWNE 1650FNL 2210FEL					LEA COUNTY, NM	
12. CHECK APP	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF	NOTICE, R	EPORT, OR OTHER	R DATA
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION					
■ Notice of Intent	☐ Acidize	☐ Deepen ☐ Pro		☐ Product	ion (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	□ Frac	ture Treat	□ Reclam	ation	■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	□ Recomp	olete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon ☐ Temp		□ Tempor	arily Abandon	
•	☐ Convert to Injection	rt to Injection 🔀 Plug Back 🔲 Water		□ Water I	Disposal	
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for following complete is ready for following complete involved that the site is ready for following complete is ready for following complete involved in the site is ready for following complete involved in the site is ready for following complete involved in the site is ready for following complete involved in the site is ready for following complete involved in the site is ready for following complete involved in the site in the si	ork will be performed or provided to operations. If the operation rebandonment Notices shall be fill final inspection.) Frow gas pay current per and government environment unsafe work. IU BOP. Obtain backside wab tog as necessary to rior FL shot), unseat pack lubricator w/fresh water, possibly up to 5 yrs), tie-ir 94 and set @ 13400 (Suit) OCH and RIH w/GR/CCL and collar log for collars. Sho	e the Bond No. or esults in a multipled only after all in fs are non pro- ent and safety FL shot. Set the remove annulated and pull rerror use KCL. RIH no to Schlumber and Baker 3-1	a file with BLM/BI e completion or reception or reception or reception of the completion of the comple	A. Required su completion in a ding reclamation yone on job packer nipp ackside volument of 15-1/2 modificular strip is. Use SLB	bsequent reports shall be new interval, a Form 3160 n, have been completed, a location le. RIH ne is fied	filed within 30 days 0-4 shall be filed once
14. I hereby certify that the foregoing i	Electronic Submission	ENERGY COM	PANY, sent to t	he Hobbs	-	
Name(Printed/Typed) BEVERLY HATFIELD			Title AUTHORIZED SIGNATURE			
Signature (Electronic	Date 09/23/	2004				
	THIS SPACE F	OR FEDERA	L OR STATE	OFFICE U	SE	
_Approved By_GARY_GOURLEY			TitlePETROL	EUM ENGIN	EER	Date 09/24/2004
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Hobbs			



Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #36609 that would not fit on the form

32. Additional remarks, continued

13292 -13320 (36 total 2 runs). Shoot the well underbalanced if possible (max anticipated BHP is ~1300psi), and minimize the amount of water contacted on new perfs do not need to load hole before perf. Leave well SI while perforating. POOH w/guns, RD eline unit.

4.RIH w/production string and re-dressed Baker packer set packer ~13160 (pressure test packer according to Hobbs OCD district regs).

5.Leave well SI overnight to build pressure put on production the next day.