

New Mexico Oil Conservation Division, District I
1625 N. French Drive
Hobbs, NM 88240

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

5. Lease Designation and Serial No.

NM-104764

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Bilbrey "30" Federal #5

9. API Well No.

30-025-33647

10. Field and Pool, or Exploratory Area

11. County or Parish, State

Lea County

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

CHI OPERATING, INC.

3. Address and Telephone No.

P.O. BOX 1799 MIDLAND, TEXAS 79702

4. Location of Well (Footage, T., R., M., or Survey Description)

1980 FSL & 1980 FEL, J-30-21S-32E

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report nature of multiple completion on Well Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work if well is

directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- Perforate 5 1/2" casing @ 855' & Squeeze w/ sufficient Cement (+40sx) To Have Solid Plug In & Out F/ 755-855' Tag
1) RD DD PU. POOH w/RBP, pkr and 2-7/8" production tbg.
2) Dump 3sx cmt on top of RBP @ 6700' to abandon all Brushy Canyon perms.
3) Set CIBP @ 4550' (above Bell Canyon) and spot 35' of cmt on top - Tag
4) Spot 100' surface plug. Perforate 5 1/2" casing @ 100' & Squeeze w/ sufficient Cement (+40sx) To Circulate To Surface &
5) Cut off well head. Install dry hole marker and reclaim location.

14. I hereby certify that the foregoing is true and correct

Signed David R. Glass Title REGULATORY CLERK Date 9/29/04

(This space for Federal or State office use)

Approved by (ORIG. SGD.) DAVID R. GLASS

Conditions of approval, if any: Title _____ Date OCT 01 2004

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

This Well Must be Plugged By 12/01/2004 To
Satisfy The Requirements For INC AJM-L169-4!
Approval Of This Notice Of Intent To Abandon
Alone Does Not Satisfy The Requirements Of
INC AJM-L169-4!

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

GWW

Name: 830.5 ID: 30025336470000 Type: DEL Date: 19981013
KB: 3692.0 TD: 8916.0 PBTD: 6700.0 Comp Date: 0

Proposed P: A

