Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	May 27, 2004
District II		WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION	30-025-11149 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505		141560
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS DEALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLI	CATION FOR PERMIT" (FORM C-101) FOR SUCH	Cooper Initiation
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well 🗌 Other 🖬 🖬	Cooper Jal Unit8. Well Number242 w
2. Name of Operator		9. OGRID Number 193003
	SDG Resources L. P.	7. OGIUD (Millioci 175005
3. Address of Operator	P. O. Box 1390	10. Pool name or Wildcat JALMAT:
	Montrose, CO 81402	Yates & 7-Rivers.
4. Well Location		
Section 10 Township 246 D ACD AND ACD AND AND AND AND AND AND AND AND AND AN		
	Township24SRange36E11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
	3311' KB	
Pit or Below-grade Tank Application or Closure		
Pit type_DIRTDepth to Groundwater_	_350 feetDistance from nearest fresh water well_>1000 feet	t_ Distance from nearest surface water_>1000 feet
Pit Liner Thickness: 200 mil Below-Grade Tank: Volume 200 bbls; Construction Material Synthetic		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK A PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	
OTHER: Repair Casing leak.		_
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
Repair Casing leak.		
Fine Case B com		21222332
1. MIRU PU.		1415167 141517 1
 Pull out of hole with 2 3/8" IPC tubing and 5 1/2" x 2 3/8" AD-1 packer. Repair casing leak and test to 500 psig. 		
 Puthout of hole with 2 3/8 TPC tubing and 5 ½ x 2 3/8" AD-1 packer. Repair casing leak and test to 500 psig. Run in hole with re-dressed AD-1 packer. Hydrotest 2 3/8" IPC tubing in hole. Land packer at 2884'. Circulate annulus with 100 barrels of inhibited packer fluid. Set AD-1 packer with 20,000# tension. 		
5. Hydrotest 2 3/8" IPC tubing in hole.		
6. Land packer at 2884'. Circulate annulus with 100 barrels of inhibited packer fluid.		
 Set AD-1 packer with 20,000# tension. Test casing and packer to 500# for 30 minutes. Pull pressure chart for NMOCD. 		
 Place well on injection at approximately 350 bwpd. 		
10. Maximum permitted injection	pressure is 600 psig.	6829546
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-		
grade tank has been/will be constructed or closed according to NMOCD guidelines 🔀, a general permit 🗌 or an (attached) alternative OCD-approved plan [].		
SIGNATURE Longing Calegolos		
Type or print name	0	
For State Use Only	E-mail address: Domingo@sdgres	ources.com Telephone No. 432-550-7580
APPROVED BY: Hand Will OC FIELD REPRESENTATIVE II/STAFF MANAGEBATE OCT 1 8 2004		
Conditions of Approval (if any)		

