Submit 3 Copies To Appropriate District	State of]			Form C-103		
Office District <u>I</u>	Energy, Minerals and Natural Resources			Revised June 10, 2003		
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-025-34206			
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	tesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type	of Lease	
<u>District III</u> 1220 South St. Francis Dr.			STATE	☐ FEE ☒		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505			6. State Oil & Ga	as Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM				•		
87505 SUNDRY NOTI	CES AND REPORTS OF	N WELLS		7. Lease Name o	r Unit Agreement Na	me
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					_	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				J. Cooper		
1. Type of Well:				8. Well Number		
Oil Well Gas Well Other				1		
2. Name of Operator				9. OGRID Number		
Me-Tex Oil & Gas, Inc.				014462		
3. Address of Operator			10. Pool name or Wildcat Northwest Skaggs Drinkard			
P.O. Box 2070 , Hobbs, NM 88241				Normwest Skagg	S Dillikalu	
4. Well Location						
Unit Letter B:	560 feet from the	North	line and 18	64 feet from the	Eastline	
					_	
Section 3 Township 20S Range 37E NMPM County Lea						
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3561' GR						
12 Chack /	Appropriate Box to In	dicate N	ature of Notice	Report or Other	Data	300 (1000-00)
		dicate 1	SUB	SEQUENT RE	PORT OF	
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR					ALTERING CASING	∍ □
, 214 07411 (121120 II 2 1 1 0 1 II 1		_				_
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE		CASING TEST A	ND 🗆	ABANDONWENT	
TOLE ON THE PER OF TOLER	COMPLETION	_	CEMENT JOB		·	
OTHER:		П	OTHER:			
	leted operations (Clearly	state all	pertinent details, an	d give pertinent dat	es, including estimate	ed date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion						
or recompletion.						
•						
 Kill well with 20 bbls. Brine water, release pkr. and P.O.H. Perforate upper drinkard with 4" Select-Fire Guns, 2 JSPF, 180 degree phasing as follows: 6,521', 25', 30', 39', 44', 45', 						
2. Perforate upper drinka:	RR' and 96' (total 26 hole	us, 2 Jorr es) Set Ai	rrow-set Pkr. @ 5.7	00'.	,23,30,37,44,4	Ι,
51', 61', 71', 77', 83', 88', and 96' (total 26 holes). Set Arrow-set Pkr. @ 5,700'. 3. Acidized perfs. 6,521' – 6,596' w/3,500 gals. 20% NeFe Hcl acid w/ball sealers.						
4. Flowed for clean-up and returned to gas sales line.						
E K- Hopps 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5						
				418	29	
				12	HODOS	/
				Sec.		
				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	30 1V/	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE						
Type or print name Tonia Harper	∥ F-mail addn	ess: than	per@zianet.com	Telephone No	o. 505-397-7750	
(This space for State use) /	, A I			_ 0.00.000 1 1		
APPPROVED BY Saw W. W. W. OC. FIELD REPRESENTATIVE ILISTAFF MANAGER DATE DET 2 5 2014						
	il winks	FIFLE RE	PRESENTATIVE II	STAFF MANAGE	R DATE 007 2 5	20 04
APPPROVED BY XOMY (Conditions of approval, if any:	e Winkoc	FIFLD RE	PRESENTATIVE II,	/STAFF MANAGE	R DATE 007 2 5	20 04