

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO.  
30025-34783

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement  
Name:

SOUTH SHOE BAR '10' STATE COM

8. Well No.

2

9. Pool name or Wildcat  
VACUUM ATOKA MORROW NORTH

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator  
CONCHO RESOURCES INC.

3. Address of Operator  
110 W. LOUISIANA STE 410; MIDLAND TX 79701

4. Well Location

Unit Letter E : 1800 feet from the North line and 990 feet from the West line

Section 10 Township 17S Range 35E NMPM LEA County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3964' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: PLUG & ABANDON ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

06-19-00 SPOT PLUG @ 12850-12750'; SPOT PLUG @ 11823-11723'; SPOT PLUG @ 9862-9762';  
SPOT PLUG @ 8596-8496'; SPOT PLUG @ 6440-6340'.

06-20-00 SET SHOE PLUG @ 5060-4960'; WOC TAG PLUG @ 4940'. SPOT PLUG @ 2021-1921';  
SPOT PLUG @ 15-415'; SPOT SURFACE PLUG @ 60' TO SURFACE. INSTALL P&A MARKER. RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terri Stathem TITLE Production Analyst DATE 06/22/00

Type or print name Terri Stathem Telephone No. 915-683-7443

(This space for State use)

APPROVED BY Johnny Robinson TITLE COMPLIANCE OFFICER DATE NOV 01 2001

Conditions of approval, if any:

IC GWW

