

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/> Observation Well	WELL API NO. 30-025-03792
2. Name of Operator Pure Resources	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator 500 W Illinois - Midland Texas 79701	6. State Oil & Gas Lease No. B-7766
4. Well Location Unit Letter <u>  </u> : <u>K</u> <u>1650</u> feet from the <u>  </u> South <u>  </u> line and <u>2310</u> feet from the <u>  </u> West <u>  </u> line Section <u>36</u> Township <u>16S</u> Range <u>36E</u> NMPM <u>  </u> Lea <u>  </u> County <u>  </u>	7. Lease Name or Unit Agreement Name: Lovington Paddock Unit
	8. Well No. 83
	9. Pool name or Wildcat Lovington Paddock Unit
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Temporarily Abandoned ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Tubing & 5 1/2" casing communicated. Ran in with a RBP and Packer. Set RBP at 5909' Set Packer at 5897'. Test RBP to 500# Pressure held. Test casing from Packer to surface. Lost 20# in 30 minutes. Pull out of hole with tubing, Packer and RBP. Ran in with a CIBP. Set @ 5960' dumped 20' cmt. on top. Circulated packer fluid. MIT 650# 30 minutes 650# no loss. Well is TA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Darryl Ruthardt TITLE Asst. Foreman DATE Nov. 4 2004

Type or print name Darryl Ruthardt Telephone No. 505-396-7503

(This space for State use)

APPROVED BY Gay W. Wink OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE NOV 10 2004

Conditions of approval, if any:

This Approval of Temporary Abandonment Expires 11/3/09



