

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-07645

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
South Hobbs (G/SA) Unit

8. Well Number
116

9. OGRID Number

10. Pool name or Wildcat
Hobbs (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other **Injector**

2. Name of Operator
Occidental Permian, Ltd.

3. Address of Operator
1017 W. Stanolind Rd. Hobbs, NM 88240

4. Well Location
Unit Letter **O** : **990** feet from the **South** line and **1650** feet from the **East** line
Section **6** Township **19S** Range **38E** NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3642' KB

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL **O** Sect **6** Twp **19S** Rng **38E** Pit type **Steel** Depth to Groundwater **76'** Distance from nearest fresh water well **Over 1000'**
Distance from nearest surface water _____ Below-grade Tank Location UL _____ Sect _____ Twp _____ Rng _____
feet from the _____ line and _____ feet from the _____ line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐


SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐



13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/16/04 Set CIBP @ 3800' Tag CIBP w/ tbq. Circ. well w/ plugging mud. Spot 20 sks of cement 3800'-3608'
Spot 25 sks of cement @ 2705'-2451'. Perf @ 1725' Pressured up on perfs to 1000 psi-Held. EL Gonzles ok'd test.
Spot 20 sks of cement @ 1784'Tagged TOC @ 1610' EL Gonzales ommited perf @ 355' (prior sqz job)
Spot 45 sks @ 395'-surface.

Cut off wellhead & anchors 3' BGL. Cap well. Install dry hole marker.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE *Jack Shelton* TITLE Agent DATE 6/21/04

Type or print name **Jack Shelton**
(This space for State use)

E-mail address: **jshelton@keyenergy.com**

Telephone No. **432-523-5155**

APPROVED BY

ORIGINAL SIGNED BY

Gary Wink
GARY WINK

DATE **NOV 22 2004**

Conditions of approval, if any:

OG FIELD REPRESENTATIVE II/STAFF MANAGER