Submit 3 Copies To Appropriate District Office	State of New		Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and	Natural Resources	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVAT	ION DIVISION	30-025-11290
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St.		5. Indicate Type of Lease STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NI	M 87505	6. State Oil & Gas Lease No.
87505	I And I Was a series of the se		141560
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	CATION FOR PERMIT" (FORM C-10	01) FOR SUCH	Cooper Jal Unit
1. Type of Well: Oil Well	Gas Well Other X	Injector	8. Well Number 228 w
2. Name of Operator	SDG Resources L. P.		9. OGRID Number 193003
3. Address of Operator	P. O. Box 1390		10. Pool name or Wildcat JALMAT:
	Montrose, CO 81401		Tansill, Yates & 7-Rivers
4. Well Location			
Unit LetterC	660feet from theNO	RTH line and1	1917feet from the WEST line
Section 30	Township 24S	Range 37E	NMPM LEA County
	11. Elevation (Show whethe 3.2)	<i>r DR, RKB, RT, GR, etc.)</i> 76' DF	
Pit or Below-grade Tank Application	or Closure 🔲		
1 7 7			Distance from nearest surface water_>1000 feet
Pit Liner Thickness: 200 mil	Below-Grade Tank: Volume		on Material Synthetic
12. Cneck	Appropriate Box to Indica	ite Nature of Notice,	Report or Other Data
	ITENTION TO:		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲	REMEDIAL WORI	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	
TEMPORARILY ABANDON DULL OR ALTER CASING	_	COMMENCE DRII CASING/CEMENT	LLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	LLING OPNS. P AND A
PULL OR ALTER CASING  OTHER: Clean out injector w/Coil  13. Describe proposed or com	MULTIPLE COMPL  ed Tubing and Acidize.  Deleted operations. (Clearly state	CASING/CEMENT OTHER: e all pertinent details, and	LLING OPNS. P AND A  JOB  I give pertinent dates, including estimated date
OTHER: Clean out injector w/Coil  13. Describe proposed or compost of starting any proposed w	MULTIPLE COMPL  ed Tubing and Acidize.  Deleted operations. (Clearly state	CASING/CEMENT OTHER: e all pertinent details, and	LLING OPNS. P AND A
OTHER: Clean out injector w/Coil  13. Describe proposed or compostarting any proposed wor recompletion.	MULTIPLE COMPL  ed Tubing and Acidize.  pleted operations. (Clearly statork). SEE RULE 1103. For M	OTHER: e all pertinent details, and fultiple Completions: Att	LLING OPNS. P AND A  JOB  I give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER: Clean out injector w/Coil  13. Describe proposed or compost of starting any proposed w	MULTIPLE COMPL  ed Tubing and Acidize.  pleted operations. (Clearly statork). SEE RULE 1103. For M	OTHER: e all pertinent details, and fultiple Completions: Att	LLING OPNS. P AND A  JOB  I give pertinent dates, including estimated date ach wellbore diagram of proposed completion
PULL OR ALTER CASING  OTHER: Clean out injector w/Coil  13. Describe proposed or compost starting any proposed wor recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit.	MULTIPLE COMPL  ed Tubing and Acidize.  bleted operations. (Clearly statork). SEE RULE 1103. For Mark/Coiled Tubing and Acidize w	OTHER: e all pertinent details, and fultiple Completions: Att	LLING OPNS. P AND A  JOB  I give pertinent dates, including estimated date ach wellbore diagram of proposed completion
PULL OR ALTER CASING  OTHER: Clean out injector w/Coil  13. Describe proposed or composed was or recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit. 2. RIH 1 ¼" Perf-Clean Tool on	MULTIPLE COMPL  ed Tubing and Acidize.  bleted operations. (Clearly statork). SEE RULE 1103. For Mark Mark Mark Mark Mark Mark Mark Mar	OTHER: e all pertinent details, and fultiple Completions: Att ith 4,000 gallons 15% NE	I give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER: Clean out injector w/Coil  13. Describe proposed or composed was or recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit. 2. RIH 1 1/4" Perf-Clean Tool on 3. Energize Tool and clean out Poly. 4. Acidize Perfs 3,040'-3,120' w	MULTIPLE COMPL  ed Tubing and Acidize.  Deted operations. (Clearly statork). SEE RULE 1103. For Mark Modern	OTHER: e all pertinent details, and fultiple Completions: Att ith 4,000 gallons 15% NE	I give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER: Clean out injector w/Coil  13. Describe proposed or compostarting any proposed wor recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit. 2. RIH 1 1/4" Perf-Clean Tool on 3. Energize Tool and clean out Polymonth 1. Acidize Perfs 3,040'-3,120' w  5. POOH with coiled tubing and	MULTIPLE COMPL  ed Tubing and Acidize.  Deted operations. (Clearly statork). SEE RULE 1103. For Mark Modern	OTHER: e all pertinent details, and fultiple Completions: Att ith 4,000 gallons 15% NE	I give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER: Clean out injector w/Coil  13. Describe proposed or composition of starting any proposed wor recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit. 2. RIH 1 ¼" Perf-Clean Tool on 3. Energize Tool and clean out Polymonth of the proposed work of the proposed with the proposed work of the proposed	MULTIPLE COMPL  ed Tubing and Acidize.  pleted operations. (Clearly state ork). SEE RULE 1103. For Mark of the control of the	OTHER: e all pertinent details, and fultiple Completions: Att ith 4,000 gallons 15% NE	I give pertinent dates, including estimated date ach wellbore diagram of proposed completion  EFE HCl acid.
OTHER: Clean out injector w/Coil  13. Describe proposed or composition of starting any proposed wor recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit. 2. RIH 1 ¼" Perf-Clean Tool on 3. Energize Tool and clean out Polymonth of the proposed work of the proposed with the proposed work of the proposed	MULTIPLE COMPL  ed Tubing and Acidize.  pleted operations. (Clearly statork). SEE RULE 1103. For Markovich and Acidize with 4,000 gallons 15% NEFE Hrig down Perf-Clean Tool.	OTHER: e all pertinent details, and fultiple Completions: Att ith 4,000 gallons 15% NE	I give pertinent dates, including estimated date ach wellbore diagram of proposed completion  EFE HCl acid.
OTHER: Clean out injector w/Coil  13. Describe proposed or composition of starting any proposed wor recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit. 2. RIH 1 ¼" Perf-Clean Tool on 3. Energize Tool and clean out Polymonth of the perfect of the perfec	MULTIPLE COMPL  ed Tubing and Acidize.  pleted operations. (Clearly statork). SEE RULE 1103. For Markovich and Acidize with 4,000 gallons 15% NEFE Hrig down Perf-Clean Tool.	OTHER: e all pertinent details, and fultiple Completions: Att ith 4,000 gallons 15% NE	I give pertinent dates, including estimated date ach wellbore diagram of proposed completion  EFE HCl acid.
OTHER: Clean out injector w/Coil  13. Describe proposed or compostarting any proposed wor recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit. 2. RIH 1 1/4" Perf-Clean Tool on 3. Energize Tool and clean out Polymonth of the proposed work of the proposed with the proposed work of the proposed with the proposed work of the	MULTIPLE COMPL  ed Tubing and Acidize.  Deted operations. (Clearly state ork). SEE RULE 1103. For Mark Coiled Tubing and Acidize was 1 1/4" coil tubing to 2,988".  erfs 3,040'-3,120' with surfact ith 4,000 gallons 15% NEFE Hrig down Perf-Clean Tool.  eximately 280 bwpd.  pressure is 600 psig.	CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: Att ith 4,000 gallons 15% NE ant water. Cl acid.	I give pertinent dates, including estimated date ach wellbore diagram of proposed completion  EFE HCl acid.  ODD SQQQQH ODD SQQQH ODD SQ
OTHER: Clean out injector w/Coil  13. Describe proposed or composition of starting any proposed wor recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit. 2. RIH 1 ¼" Perf-Clean Tool on 3. Energize Tool and clean out Polymonth of the proposed work of the propos	MULTIPLE COMPL  ed Tubing and Acidize.  pleted operations. (Clearly state ork). SEE RULE 1103. For Mark of the control of the	CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: Att ith 4,000 gallons 15% NE ant water. Cl acid.	I give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER: Clean out injector w/Coil  13. Describe proposed or composition of starting any proposed wor recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit. 2. RIH 1 ¼" Perf-Clean Tool on 3. Energize Tool and clean out Polymonth of the proposed work of the propos	MULTIPLE COMPL  ed Tubing and Acidize.  pleted operations. (Clearly state ork). SEE RULE 1103. For Mark of the control of the	CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: Att ith 4,000 gallons 15% NE ant water. Cl acid.	and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
OTHER: Clean out injector w/Coil  13. Describe proposed or composition of starting any proposed wor recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit. 2. RIH 1 ¼" Perf-Clean Tool on 3. Energize Tool and clean out P 4. Acidize Perfs 3,040'-3,120' w 5. POOH with coiled tubing and 6. RD Coiled Tubing Unit. 7. Place well on injection at appr 8. Maximum permitted injection  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	MULTIPLE COMPL  and Tubing and Acidize.  bleted operations. (Clearly state ork). SEE RULE 1103. For Mark Moreon Mo	CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: Att ith 4,000 gallons 15% NE ant water. Cl acid.  the best of my knowledge elines 2, a general permit  LE_Senior Petroleum En	and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE_11/10/04_
OTHER: Clean out injector w/Coil  13. Describe proposed or composition of starting any proposed wor recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit. 2. RIH 1 ¼" Perf-Clean Tool on 3. Energize Tool and clean out Pour Pool of the proposed work of the propos	MULTIPLE COMPL  and Tubing and Acidize.  bleted operations. (Clearly state ork). SEE RULE 1103. For Mark Moreon Mo	CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: Att ith 4,000 gallons 15% NE ant water. Cl acid.  the best of my knowledge elines 2, a general permit  LE_Senior Petroleum En	I give pertinent dates, including estimated date ach wellbore diagram of proposed completion  EFE HCl acid.  and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE_11/10/04_ crees.com Telephone No. 432-550-7580
OTHER: Clean out injector w/Coil  13. Describe proposed or come of starting any proposed we or recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit. 2. RIH 1 ¼" Perf-Clean Tool on 3. Energize Tool and clean out P 4. Acidize Perfs 3,040'-3,120' w 5. POOH with coiled tubing and 6. RD Coiled Tubing Unit. 7. Place well on injection at appr 8. Maximum permitted injection  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE  Type or print name  For State Use Only	MULTIPLE COMPL  and Tubing and Acidize.  bleted operations. (Clearly state ork). SEE RULE 1103. For Mark Moreon Mo	CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: Att ith 4,000 gallons 15% NE ant water. Cl acid.  the best of my knowledge elines 25, a general permit  LE_Senior Petroleum Entress: Domingo@sdgresou	I give pertinent dates, including estimated date ach wellbore diagram of proposed completion  EFE HCl acid.  and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE_11/10/04_ arces.com Telephone No. 432-550-7580  NOV 2 2 2004
OTHER: Clean out injector w/Coil  13. Describe proposed or composition of starting any proposed wor recompletion.  Objective: Clean out injector w  1. MIRU Coiled Tubing Unit. 2. RIH 1 ¼" Perf-Clean Tool on 3. Energize Tool and clean out P 4. Acidize Perfs 3,040'-3,120' w 5. POOH with coiled tubing and 6. RD Coiled Tubing Unit. 7. Place well on injection at appr 8. Maximum permitted injection  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	MULTIPLE COMPL  and Tubing and Acidize.  bleted operations. (Clearly state ork). SEE RULE 1103. For Mark Moreon Mo	CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: Att ith 4,000 gallons 15% NE ant water. Cl acid.  the best of my knowledge elines 25, a general permit  LE_Senior Petroleum Entress: Domingo@sdgresou	I give pertinent dates, including estimated date ach wellbore diagram of proposed completion  EFE HCl acid.  and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE_11/10/04_ crees.com Telephone No. 432-550-7580

