State of New Mexico

Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Submit 3 copies to Appropriate District Office

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O

DIS

100

OIL CONSERVATION DIVISION

P.O.	Box	2088	

Santa Fe. New Mexico 87504-2088

30-025-35694

WELL API NO.

5. Indicate Type of Lease

STATE FEE 🗹	
6. State Oil / Gas Lease No.	
o. Clate Oil / Cas Lease No.	
7. Lease Name or Unit Agreement Name	
T T T T T T T T T T T T T T T T T T T	
LOVE 32	
8. Well No.	
3	
9. Pool Name or Wildcat	
MONUMENT TUBB	
Feet From The EAST Line	
NMPM <u>LEA</u> COUNTY	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

GL 3559'

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPERATION	PLUG AND ABANDONMENT	
PULL OR ALTER CASING		•		CASING TEST AND CEMENT JOB]	
OTHER:			_ 🗆	OTHER: REF	PAIR CSG LEAK	_

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-26-04: MIRU KEY #331.

10-27-04: TOH & LD RDS.

10-28-04: REL TAC. TOH & LD PROD TBG. 10-29-04: TAG FILL @ 6530. C/O FILL FR 6530-6645.

11-01-04: TIH W/RBP & PKR. SET RBP @ 6480. ISOLATE CSG LEAK FR 4228-4260.. TIH & LATCH RBP. PUH & SET RBP @ 4426. DUMP 20' SAND ON TOP OF RBP. TOH W/PKR. TIH W/CICR TO 4043.

11-02-04: SQZ CSG LEAK FR 4228-4260. START LEAD SLURRY OF 200 SX. PUMP TAIL CMT OF 150 SX CL C CMT.

10. Elevation (Show whether DF, RKB, RT,GR, etc.)

11-03-04: CMT CSG ANN W/300 SX CMT & TAIL W/150 SX CL C. REV OUT 1 BBL CMT.

11-04-04: TIH W/TBG. DRILL HARD CMT TO 4043. DRILL ON CMT RET @ 4043 TO 4062. PUSH RET THRU CMT.

11-05-04: D/O SOLID CMT FR 4062-4186. CMT STRINGERS FR 4186-4249. SOLID CMT FR 4249-81. FELL OUT OF CMT @ 4281. WASH TO 4312. TEST SQZ TO 700# FOR 30 MIN. TAG SAND @ 4410. WASH SD TO RBP @ 4425. REL RBP @ 4425. TIH W/PKR & SET @ 6378.

11-08-04: ACIDIZE TUBB PERFS 6494-6583 W/2500 GALS 15% ANTI-SLUDGE HCL. RU SWAB. REL PKR @ 6378. TIH & RESET PKR @ 6378.RU SWAB.

11-09-04: REL PKR @ 6378. SET TAC.

11-10-04: PU INSERT PUMP & RODS. RIG DOWN. TURN WELL OVER TO PRODUCTION.

FINAL REPORT



Regulatory Specialist TITLE

DATE 11/11/2004

TYPE OR PRINT NAME

Denise Leake

Telephone No. 915-687-7375

APPROVED CONDITIONS OF APPROVAL, IF ANY:

TITLE

OC FIELD REPRESENTATIVE II/STAFF MANAGE

DATE