Submit 3 Copies To Appropriate District Office State of New Mexico Minerals and Newscal Processes	Form C-103
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	March 4, 2004 WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-02191
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE ☑ FEE □
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	B-871-1
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	West Vacuum Unit
PROPOSALS.) 1. Type of Well:	8. Well Number
Oil Well Gas Well Other Injector	24
2. Name of Operator	9. OGRID Number
Chevron USA Inc	3. CORD Manior
3. Address of Operator	10. Pool name or Wildcat
15 Smith Rd, Midland, TX 79705 4. Well Location	Vacuum Grayburg San Andres
4. Well Education	
Unit Letter J: 1980 feet from the South line and	1980feet from theEastline
Section 33 Township 17-S Range 34-E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached) Pit Location: UL J Sect 33 Twp 17S Rng 34E Pit type Steel Depth to Groundwater 87 Distance from nearest curfoce water Release Toron Research Land Land Land Land Land Land Land Land	
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng \$\infty\$	
1980 feet from the South line and 1980 feet from the East line (Steel Tank)	
m (Oldor Farik)	2122. 2122. 000 212. 1000 212. 1000 212.
12 Chook Ammonisto Dou to Indiana Nature Charles	\0, -3
12. Check Appropriate Box to Indicate Nature of Notice NOTICE OF INTENTION TO:	REPORT OF Other Loata BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☑ REMEDIAL WO	
	RILLING OPNS.□ PLUG AND □ ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TEST	
COMPLETION CEMENT JOB	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	Attach wellbore diagram of proposed completion
1 Notify OCD 24 hrs prior to MI and PU	10sx Surf. Install dry hole marker.
2. RIH spot 25sx, plug from 4171-4000 (San Andres) WOC Tag.	UIL CONSERVATION DIVISION MUST
4. Perf 4 holes at 2800, sqz 50sx, plug from 2800-2600 (Yates, B-Salt) WOC Tag.	NOTIFIED 24 HOURS PRIOR TO THE
5. Cut 5 1/2" csg at 1100, L/D csg. 6. Spot 75sx, plug from 1150-850 (8 5/8 Shoe, T-Salt, Stub) WOC Tag.	INNING OF PLUGGING OPERATIONS.
	±
I hereby certify that the information above is true and complete to the best of my knowled	ge and belief. I further certify that any pit or below-
grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [」 or an (attached) alternative OCD-approved plan ∐.
SIGNATURE TITLE Consult	ant DATE 11-22-04
Type or print name Cimmy Bagley E-mail address:	Telephone No. 432-561-8600
L-man address.	Telephone No. 432-561-8600
Type or print name E-mail address: (This space for State use)	
(This space for State use)	NOV 2 4 2004
L-man address.	NOV 2 4 2004