District I Energy, Mineral	f New Mexico	Form C-103 May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	s and Natural Resources	Way 27, 2004 VELL API NO. 30-025-36884
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSER	VATION DIVISION 5	. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	th St. Francis Dr. Fe, NM 87505	STATE X FEE
District IV Santa J 1220 S. St. Francis Dr., Santa Fe, NM 87505	6, 1410 07505 6	. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ( (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FO	EPEN OR PLUG BACK TO A	. Lease Name or Unit Agreement Name State 22
PROPOSALS.) 1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other		. Well Number 003
2. Name of Operator Chesapeake Operating, Inc.	9	. OGRID Number 147179
3. Address of Operator P. O. Box 11050 Midland, TX 79702-8050	1	0. Pool name or Wildcat
4. Well Location		Trinity;Wolfcamp 59890
Unit Letter H : 1645 feet from th	e North line and 354	feet from the East line
Section 22 Township 1		MPM county bon
	whether DR, RKB, RT, GR, etc.)	Je Contraction of the second s
Pit or Below-grade Tank Application 🗌 or Closure 🛄		
Pit typeDepth to GroundwaterDistance from r	earest fresh water well Distanc	re from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: V		ruction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK D PLUG AND ABANDO TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL		
OTHER:		
<ol> <li>Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 1103.</li> </ol>	ly state all pertinent details, and g	ive pertinent dates, including estimated date h wellbore diagram of proposed completion
or recompletion. 10-03-04 Spud 17 1/2" hole @ 4:00 p.m. 10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt		in w/235 sx Cl C + additives. Circ 54
10-03-04 Spud 17 1/2" hole @ 4:00 p.m. 10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs. 10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg.	'd w/155 sx Poz C + additives, tail	
10-03-04 Spud 17 1/2" hole @ 4:00 p.m. 10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs. 10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg. w/200 sx Cl. C + additives. WOC 24 hrs. 10-25-04 In 7 7/8" hole, ran 206 jts. 5 1/2" 17# L-80 LTC	'd w/155 sx Poz C + additives, tail set @ 4500'. Cmt'd w/1800 sx 50	0:50 Poz Class "C" + additives; tail in
10-03-04 Spud 17 1/2" hole @ 4:00 p.m. 10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs. 10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg. w/200 sx Cl. C + additives. WOC 24 hrs. 10-25-04 In 7 7/8" hole, ran 206 jts. 5 1/2" 17# L-80 LTC sx 50/50 Poz H + additives.	'd w/155 sx Poz C + additives, tail set @ 4500'. Cmt'd w/1800 sx 56 csg. set @ 9265'. Cmt'd w/552 sx	0:50 Poz Class "C" + additives; tail in
10-03-04 Spud 17 1/2" hole @ 4:00 p.m. 10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs. 10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg. w/200 sx Cl. C + additives. WOC 24 hrs. 10-25-04 In 7 7/8" hole, ran 206 jts. 5 1/2" 17# L-80 LTC sx 50/50 Poz H + additives. 10-26-04 Release Big Dog Drilling rig #13 @ 10:00 on 10 10-30-04 RIH to PBTD 9150'. pull CBL/VDL/GR/CCL fit	'd w/155 sx Poz C + additives, tail set @ 4500'. Cmt'd w/1800 sx 50 csg. set @ 9265'. Cmt'd w/552 sx 0/25/04. rom PBTD to 8000', then 5.416' ba	0:50 Poz Class "C" + additives; tail in 50:50 Poz H + additives; tail in w/400 eck to 5.000'. TOC @ 4480' RIH w/ 4"
10-03-04 Spud 17 1/2" hole @ 4:00 p.m. 10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs. 10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg. w/200 sx Cl. C + additives. WOC 24 hrs. 10-25-04 In 7 7/8" hole, ran 206 jts. 5 1/2" 17# L-80 LTC sx 50/50 Poz H + additives. 10-26-04 Release Big Dog Drilling rig #13 @ 10:00 on 10 10-30-04 RIH to PBTD 9150'. pull CBL/VDL/GR/CCL fi slick perf. gun. Perforate Wolfcamp 9,043 - 9063', 41 hole	'd w/155 sx Poz C + additives, tail set @ 4500'. Cmt'd w/1800 sx 50 csg. set @ 9265'. Cmt'd w/552 sx 0/25/04. rom PBTD to 8000', then 5.416' ba	0:50 Poz Class "C" + additives; tail in 50:50 Poz H + additives; tail in w/400 eck to 5.000'. TOC @ 4480' RIH w/ 4"
10-03-04 Spud 17 1/2" hole @ 4:00 p.m. 10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs. 10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg. w/200 sx Cl. C + additives. WOC 24 hrs. 10-25-04 In 7 7/8" hole, ran 206 jts. 5 1/2" 17# L-80 LTC sx 50/50 Poz H + additives. 10-26-04 Release Big Dog Drilling rig #13 @ 10:00 on 10 10-30-04 RIH to PBTD 9150'. pull CBL/VDL/GR/CCL fi slick perf. gun. Perforate Wolfcamp 9,043 - 9063', 41 hole 6.5# EUE 8RD L-80 tbg. Set pkr. @ 8,995'. 11-02-04 RU Cudd Pmpg Serv. Press. csg. to 2000 psi - 0	'd w/155 sx Poz C + additives, tail set @ 4500'. Cmt'd w/1800 sx 50 csg. set @ 9265'. Cmt'd w/552 sx 0/25/04. om PBTD to 8000', then 5,416' ba s. Perforate 9063 - 9070' 14 holes k. Load csg. w/20 bbls 2% KCL, t	0:50 Poz Class "C" + additives; tail in 50:50 Poz H + additives; tail in w/400 ock to 5,000'. TOC @ 4480'. RIH w/ 4" (55 holes total) RIH w/ 238 jts. 2 7/8" press. to 1500#. leak. POOH w/nkr. RIH
10-03-04 Spud 17 1/2" hole @ 4:00 p.m. 10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs. 10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg. w/200 sx Cl. C + additives. WOC 24 hrs. 10-25-04 In 7 7/8" hole, ran 206 jts. 5 1/2" 17# L-80 LTC sx 50/50 Poz H + additives. 10-26-04 Release Big Dog Drilling rig #13 @ 10:00 on 10 10-30-04 RIH to PBTD 9150'. pull CBL/VDL/GR/CCL fi slick perf. gun. Perforate Wolfcamp 9,043 - 9063', 41 hole 6.5# EUE 8RD L-80 tbg. Set pkr. @ 8,995'. 11-02-04 RU Cudd Pmpg Serv. Press. csg. to 2000 psi - o w/new pkr set @ 9064 w/20000# compression. Acidize Wo	'd w/155 sx Poz C + additives, tail set @ 4500'. Cmt'd w/1800 sx 50 csg. set @ 9265'. Cmt'd w/552 sx 0/25/04. om PBTD to 8000', then 5,416' ba s. Perforate 9063 - 9070' 14 holes k. Load csg. w/20 bbls 2% KCL, t	0:50 Poz Class "C" + additives; tail in 50:50 Poz H + additives; tail in w/400 ock to 5,000'. TOC @ 4480'. RIH w/ 4" (55 holes total) RIH w/ 238 jts. 2 7/8" press. to 1500#. leak. POOH w/nkr. RIH
10-03-04 Spud 17 1/2" hole @ 4:00 p.m. 10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs. 10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg. w/200 sx Cl. C + additives. WOC 24 hrs. 10-25-04 In 7 7/8" hole, ran 206 jts. 5 1/2" 17# L-80 LTC sx 50/50 Poz H + additives. 10-26-04 Release Big Dog Drilling rig #13 @ 10:00 on 10 10-30-04 RIH to PBTD 9150'. pull CBL/VDL/GR/CCL fi slick perf. gun. Perforate Wolfcamp 9,043 - 9063', 41 hole 6.5# EUE 8RD L-80 tbg. Set pkr. @ 8,995'. 11-02-04 RU Cudd Pmpg Serv. Press. csg. to 2000 psi - o w/new pkr set @ 9064 w/20000# compression. Acidize Wo Swabbing	'd w/155 sx Poz C + additives, tail set @ 4500'. Cmt'd w/1800 sx 50 csg. set @ 9265'. Cmt'd w/552 sx 0/25/04. om PBTD to 8000', then 5,416' ba s. Perforate 9063 - 9070' 14 holes k. Load csg. w/20 bbls 2% KCL, t	0:50 Poz Class "C" + additives; tail in 50:50 Poz H + additives; tail in w/400 ock to 5,000'. TOC @ 4480'. RIH w/ 4" (55 holes total) RIH w/ 238 jts. 2 7/8" press. to 1500#. leak. POOH w/nkr. RIH
10-03-04 Spud 17 1/2" hole @ 4:00 p.m. 10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs. 10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg. w/200 sx Cl. C + additives. WOC 24 hrs. 10-25-04 In 7 7/8" hole, ran 206 jts. 5 1/2" 17# L-80 LTC sx 50/50 Poz H + additives. 10-26-04 Release Big Dog Drilling rig #13 @ 10:00 on 10 10-30-04 RIH to PBTD 9150'. pull CBL/VDL/GR/CCL fi slick perf. gun. Perforate Wolfcamp 9,043 - 9063', 41 hole 6.5# EUE 8RD L-80 tbg. Set pkr. @ 8,995'. 11-02-04 RU Cudd Pmpg Serv. Press. csg. to 2000 psi - o w/new pkr set @ 9064 w/20000# compression. Acidize Wo Swabbing 11-06-04 Frac WC w/10,000 gals Ultragel. 11-10-04 RIH w/2 1/2" x 1 1/2" x 20' RHBM pump.	'd w/155 sx Poz C + additives, tail set @ 4500'. Cmt'd w/1800 sx 50 csg. set @ 9265'. Cmt'd w/552 sx 0/25/04. om PBTD to 8000', then 5,416' ba s. Perforate 9063 - 9070' 14 holes k. Load csg. w/20 bbls 2% KCL, t	0:50 Poz Class "C" + additives; tail in 50:50 Poz H + additives; tail in w/400 ock to 5,000'. TOC @ 4480'. RIH w/ 4" (55 holes total) RIH w/ 238 jts. 2 7/8" press. to 1500#. leak. POOH w/nkr. RIH
<ul> <li>10-03-04 Spud 17 1/2" hole @ 4:00 p.m.</li> <li>10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs.</li> <li>10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg. w/200 sx Cl. C + additives. WOC 24 hrs.</li> <li>10-25-04 In 7 7/8" hole, ran 206 jts. 5 1/2" 17# L-80 LTC sx 50/50 Poz H + additives.</li> <li>10-26-04 Release Big Dog Drilling rig #13 @ 10:00 on 10 10-30-04 RIH to PBTD 9150'. pull CBL/VDL/GR/CCL fr slick perf. gun. Perforate Wolfcamp 9,043 - 9063', 41 hole 6.5# EUE 8RD L-80 tbg. Set pkr. @ 8,995'.</li> <li>11-02-04 RU Cudd Pmpg Serv. Press. csg. to 2000 psi - o w/new pkr set @ 9064 w/20000# compression. Acidize Wo Swabbing 11-06-04 Frac WC w/10,000 gals Ultragel.</li> </ul>	'd w/155 sx Poz C + additives, tail set @ 4500'. Cmt'd w/1800 sx 50 csg. set @ 9265'. Cmt'd w/552 sx 0/25/04. om PBTD to 8000', then 5,416' ba s. Perforate 9063 - 9070' 14 holes k. Load csg. w/20 bbls 2% KCL, t	0:50 Poz Class "C" + additives; tail in 50:50 Poz H + additives; tail in w/400 ock to 5,000'. TOC @ 4480'. RIH w/ 4" (55 holes total) RIH w/ 238 jts. 2 7/8" press. to 1500#. leak. POOH w/nkr. RIH
<ul> <li>10-03-04 Spud 17 1/2" hole @ 4:00 p.m.</li> <li>10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs.</li> <li>10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg. w/200 sx Cl. C + additives. WOC 24 hrs.</li> <li>10-25-04 In 7 7/8" hole, ran 206 jts. 5 1/2" 17# L-80 LTC sx 50/50 Poz H + additives.</li> <li>10-26-04 Release Big Dog Drilling rig #13 @ 10:00 on 10 10-30-04 RIH to PBTD 9150'. pull CBL/VDL/GR/CCL fi slick perf. gun. Perforate Wolfcamp 9,043 - 9063', 41 hole 6.5# EUE 8RD L-80 tbg. Set pkr. @ 8,995'.</li> <li>11-02-04 RU Cudd Pmpg Serv. Press. csg. to 2000 psi - o w/new pkr set @ 9064 w/20000# compression. Acidize We Swabbing</li> <li>11-06-04 Frac WC w/10,000 gals Ultragel.</li> <li>11-10-04 RIH w/2 1/2" x 1 1/2" x 20' RHBM pump.</li> <li>11-15-04 Placed well on production;</li> </ul>	d w/155 sx Poz C + additives, tail set @ 4500'. Cmt'd w/1800 sx 50 csg. set @ 9265'. Cmt'd w/552 sx 0/25/04. om PBTD to 8000', then 5,416' ba s. Perforate 9063 - 9070' 14 holes k. Load csg. w/20 bbls 2% KCL, j olfcamp w/5000 gals 15% HCL 90	0:50 Poz Class "C" + additives; tail in 50:50 Poz H + additives; tail in w/400 ack to 5,000'. TOC @ 4480'. RIH w/ 4" (55 holes total) RIH w/ 238 jts. 2 7/8" press. to 1500#, leak. POOH w/pkr. RIH v/10 acid + 83 BS in last 4,000 gals acid.
10-03-04 Spud 17 1/2" hole @ 4:00 p.m. 10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs. 10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg. w/200 sx Cl. C + additives. WOC 24 hrs. 10-25-04 In 7 7/8" hole, ran 206 jts. 5 1/2" 17# L-80 LTC sx 50/50 Poz H + additives. 10-26-04 Release Big Dog Drilling rig #13 @ 10:00 on 10 10-30-04 RIH to PBTD 9150'. pull CBL/VDL/GR/CCL fi slick perf. gun. Perforate Wolfcamp 9,043 - 9063', 41 hole 6.5# EUE 8RD L-80 tbg. Set pkr. @ 8,995'. 11-02-04 RU Cudd Pmpg Serv. Press. csg. to 2000 psi - o w/new pkr set @ 9064 w/20000# compression. Acidize Wo Swabbing 11-06-04 Frac WC w/10,000 gals Ultragel. 11-10-04 RIH w/2 1/2" x 1 1/2" x 20' RHBM pump. 11-15-04 Placed well on production;	d w/155 sx Poz C + additives, tail set @ 4500'. Cmt'd w/1800 sx 50 csg. set @ 9265'. Cmt'd w/552 sx 0/25/04. om PBTD to 8000', then 5,416' ba s. Perforate 9063 - 9070' 14 holes k. Load csg. w/20 bbls 2% KCL, j olfcamp w/5000 gals 15% HCL 90	0:50 Poz Class "C" + additives; tail in 50:50 Poz H + additives; tail in w/400 ack to 5,000'. TOC @ 4480'. RIH w/ 4" (55 holes total) RIH w/ 238 jts. 2 7/8" press. to 1500#, leak. POOH w/pkr. RIH v/10 acid + 83 BS in last 4,000 gals acid.
<ul> <li>10-03-04 Spud 17 1/2" hole @ 4:00 p.m.</li> <li>10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs.</li> <li>10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg. w/200 sx Cl. C + additives. WOC 24 hrs.</li> <li>10-25-04 In 7 7/8" hole, ran 206 jts. 5 1/2" 17# L-80 LTC sx 50/50 Poz H + additives.</li> <li>10-26-04 Release Big Dog Drilling rig #13 @ 10:00 on 10 10-30-04 RIH to PBTD 9150'. pull CBL/VDL/GR/CCL fr slick perf. gun. Perforate Wolfcamp 9,043 - 9063', 41 hole 6.5# EUE 8RD L-80 tbg. Set pkr. @ 8,995'.</li> <li>11-02-04 RU Cudd Pmpg Serv. Press. csg. to 2000 psi - o w/new pkr set @ 9064 w/20000# compression. Acidize Wo Swabbing</li> <li>11-06-04 Frac WC w/10,000 gals Ultragel.</li> <li>11-10-04 RIH w/2 1/2" x 1 1/2" x 20' RHBM pump.</li> <li>11-15-04 Placed well on production;</li> </ul>	'd w/155 sx Poz C + additives, tail set @ 4500'. Cmt'd w/1800 sx 50 csg. set @ 9265'. Cmt'd w/552 sx 0/25/04. om PBTD to 8000', then 5,416' ba s. Perforate 9063 - 9070' 14 holes k. Load csg. w/20 bbls 2% KCL, j olfcamp w/5000 gals 15% HCL 90 ete to the best of my knowledge at O guidelines □, a general permit □ or a _TITLE Regulatory Analyst E-mail address: bcoffman@chke	0:50 Poz Class "C" + additives; tail in 50:50 Poz H + additives; tail in w/400 eck to 5,000'. TOC @ 4480'. RIH w/ 4" (55 holes total) RIH w/ 238 jts. 2 7/8" press. to 1500#, leak. POOH w/pkr. RIH 10 acid + 83 BS in last 4,000 gals acid. md belief. I further certify that any pit or below- in (attached) alternative OCD-approved plan $\Box$ . DATE 12/06/2004 nergy.com Telephone No. (432)685-4310
<ul> <li>10-03-04 Spud 17 1/2" hole @ 4:00 p.m.</li> <li>10-04-04 Ran 13 3/8" 48# H-40 STC csg set @ 451'. Cmt sx to pit. WOC 24 hrs.</li> <li>10-12-04 In 11" hole, ran 103 jts. 8 5/8" 32# J55 LTC csg. w/200 sx Cl. C + additives. WOC 24 hrs.</li> <li>10-25-04 In 7 7/8" hole, ran 206 jts. 5 1/2" 17# L-80 LTC sx 50/50 Poz H + additives.</li> <li>10-26-04 Release Big Dog Drilling rig #13 @ 10:00 on 10 10-30-04 RIH to PBTD 9150'. pull CBL/VDL/GR/CCL fr slick perf. gun. Perforate Wolfcamp 9,043 - 9063', 41 hole 6.5# EUE 8RD L-80 tbg. Set pkr. @ 8,995'.</li> <li>11-02-04 RU Cudd Pmpg Serv. Press. csg. to 2000 psi - o w/new pkr set @ 9064 w/20000# compression. Acidize Wo Swabbing</li> <li>11-06-04 Frac WC w/10,000 gals Ultragel.</li> <li>11-10-04 RIH w/2 1/2" x 1 1/2" x 20' RHBM pump.</li> <li>11-15-04 Placed well on production;</li> </ul>	'd w/155 sx Poz C + additives, tail set @ 4500'. Cmt'd w/1800 sx 50 csg. set @ 9265'. Cmt'd w/552 sx 0/25/04. om PBTD to 8000', then 5,416' ba s. Perforate 9063 - 9070' 14 holes k. Load csg. w/20 bbls 2% KCL, j olfcamp w/5000 gals 15% HCL 90 ete to the best of my knowledge at O guidelines □, a general permit □ or a _TITLE Regulatory Analyst E-mail address: bcoffman@chke	0:50 Poz Class "C" + additives; tail in 50:50 Poz H + additives; tail in w/400 ack to 5,000'. TOC @ 4480'. RIH w/ 4" (55 holes total) RIH w/ 238 jts. 2 7/8" press. to 1500#, leak. POOH w/pkr. RIH /10 acid + 83 BS in last 4,000 gals acid.

AFFROVED DI.	
Conditions of Approv	val (if any