Form 3160-5

OCIO - Hobbs

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
Other Instructions on reve

BLM Roswell District Modified Form No. NM060-3160-4

		side)	5. LEASE DESIGNATION AND LC-067968	D SERIAL NO.	
Use "APPLICATION	ES AND REPORTS ON to drill or to deepen or plug back to FOR PERMIT-* for such proposals.)		6. IF INDIAN, ALLOTTEE OR	TRIBE NAME	
1. OIL X GAS OTHER		7. UNIT AGREEMENT NAME WEST DOLLARHIDE DRINKARD			
2. NAME OF OPERATOR TEXACO EXPLORATION AND PRODUCTION INC.			8. FARM OR LEASE NAME		
3. ADDRESS OF OPERATOR		3a. AREA CODE & PHONE NO.	9. WELL NO.		
P. O. Box 3109, Midland, TX 79702 (9 4. LOCATION OF WELL (Report location clearly and in accordance with any State requises also space 17 below.) At surface 1125' FSL & 2450' FEL, UNIT LETTER O, SW/SE		(915) 688-4620	137		
		requirements.*	10. FIELD AND POOL, OR WILDCAT DOLLARHIDE TUBB DRINKARD		
			11. SEC., T., R., M., OR BLK SURVEY OR AREA	C. AND	
			SEC. 19, T-24-S		
14. PERMIT NO. 15. ELEVATIONS (Show whether DF,		RT, GR, etc.)		13. STATE	
API#: 30-025-32088	GR-3166', KB-3179'			NM	
16. Check App	propriate Box To Indicate	Nature of Notice, Repor	rt, or Other Data		
NOTICE OF INTENTION TO: SUBSEQUE			JENT REPORT OF:		
TEST WATER SHUT-OFF P	JLL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	L 🔲	
FRACTURE TREAT	ULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASIN	ıg	
SHOOT OR ACIDIZE A	BANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*		
	HANGE PLANS	(Other) CORE & PRODUC	O NON CASING of multiple completion on W	X	
(Other) 17. DESCRIBE PROPOSED OR COMPLETED OPE		Completion or Recom	pletion Report and Log form.)	
1. DRILLED 7 7/8 HOLE TO 663 RECV. 60'. 6743-6780, RECV. RECV. 49'. 6940-6985, RECV.	37'. 6805–6842, 37'. 684 :	2–6855, RECV. 7'. 6855-			
PULLED GR-CNL TO SURFACE. 3. RAN 105 JOINTS OF 5 1/2, '7670'. 4. DOWELL CEMENTED W/ 210 94 CF/S). F/B 500 SACKS CLACIRCULATE CEMENT. 5. RAN TEMPERATURE SURVEY. 6. ND. RELEASE RIG @ 11:00 AI 7. PREP TO COMPLETE.	-SONIC FROM 7656' TO 520 15.5# J-55, 23 JOINTS 17# 0 SACKS 35/65 POZ CLASS SS H (15.6 PPG, 1.18 CF/S TOP OF CEMENT @ 1800'.	00' & GR-CSNG-CNL-LDT- WC-50 and 49 Joints 1 Hw/6% GEL, 5% Salt,	-CAL FROM 7602' TO 17# L-80. LTC CASIN 1/4# FLOCELE (12. 1/09-12-93. DID NOT	5200'. IG SET <i>@</i> 8 PPG, 1.	
PULLED GR-CNL TO SURFACE. 3. RAN 105 JOINTS OF 5 1/2, 7670'. 4. DOWELL CEMENTED W/ 210 94 CF/S). F/B 500 SACKS CLAC CIRCULATE CEMENT. 5. RAN TEMPERATURE SURVEY. 6. ND. RELEASE RIG @ 11:00 AI	-SONIC FROM 7656' TO 520 15.5# J-55, 23 JOINTS 17# 0 SACKS 35/65 POZ CLASS SS H (15.6 PPG, 1.18 CF/S TOP OF CEMENT @ 1800'. 1 09-12-93.	00' & GR-CSNG-CNL-LDT- WC-50 AND 49 JOINTS 1 H W/ 6% GEL, 5% SALT, E). PLUG DOWN @ 5:45 AN	-CAL FROM 7602' TO 17# L-80. LTC CASIN 1/4# FLOCELE (12. 1/4# FLOC	5200'. IG SET @ 8 PPG, 1.	