State of New Mexico Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

Form C-103 Revised 1-1-89

| Submit 3 copies |
|-----------------------------------|
| to Appropriate |
| to Appropriate District Office |
| District Office |

DISTRICT I

DISTRICT III

1. Type of Well:

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

1000 Rio Brazos Rd., Aztec, NM 87410

WELL

Santa Fe, New Mexico 87504-2088

P.O. Box 2088

30-025-02249

5. Indicate Type of Lease

STATE V FEE [

6. State Oil / Gas Lease No.

B-1080

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO 7. Lease Name or Unit Agreement Name

DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.

GAS

OTHER

WELL

CHEVRON USA INC

15 SMITH ROAD, MIDLAND, TX 79705

8. Well No.

WELL API NO.

41

VACUUM GRAYBURG SAN ANDRES UNIT

VACUUM GRAYBURG SAN ANDRES

3. Address of Operator

4. Well Location

2. Name of Operator

Unit Letter F: 1980 Feet From The NORTH Line and 1980

Feet From The_WEST

9. Pool Name or Wildcat

Section 1

Township 18S

Range 34E

__NMPM

LEA COUNTY

10. Elevation (Show whether DF, RKB, RT,GR, etc.)

4003' DF

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: | | | SUBSEQUENT REPORT OF: | | | | |
|-------------------------|--|------------------|-----------------------|-------------|---------------------|-----------------------|----------|
| PERFORM REMEDIAL WORK | | PLUG AND ABANDON | | REMEDIAL WO | RK 🗹 | ALTERING CASING | |
| TEMPORARILY ABANDON | | CHANGE PLANS | | COMMENCE DR | RILLING OPERATION [| PLUG AND ABANDONMENT | |
| PULL OR ALTER CASING | | | | CASING TEST | AND CEMENT JOB | | |
| OTHER: | | | | OTHER: | CLEAN OUT, ACIDIZI | E, RETURN TO SUB PUMP | V |
| | | | | | | | |

| 12. | Describe Proposed or Completed Operations proposed work) SEE RULE 1103. | (Clearly state all pertinent details | s, and give pertinent dates, including estimate | d date of starting an |
|-----|---|--------------------------------------|---|------------------------|
| | proposed work) SEE RULE 1103. | | , g , and an analy, moraling community | a date of starting any |

11-09-04: MIRU KEY #167.

11-10-04: CIRC WATER UP CSG, CSG PRESS UP.

11-11-04: PUMP 1000 GALS 15% ACID DN TBG. PUMP 2000 GALS 15% ACID.

11-12-04: WORK SUB PUMP FREE.

11-15-04: TOH W/37 JTS 2 3/8" TBG. TIH W/132 JTS 2 3/8" PROD TBG.

11-16-04: PU BHA: WP, BMPR SUB, JARS, DC'S, 2 7/8" WS TO 4003.

11-17-04: C/O TO 4009. TIH W/WS, DC, JARS, BMPR SUBS. TIH W/OD SHOE. TAG UP @ 4009.

11-18-04: TIH W/TAPER MIL, BMPR SUBS, JARS & WS. TAG UP @ 4009. MILL THRU TO 4130. TITE SPOT IN CSG @ 4009.

11-19-04: PU MILL, SUB, JARS & DC'S TO 2095.

11-22-04: TIH W/12 STANDS TO 3996'.

11-23-04: REPLACE DRUM ON PU.

11-24-04: MIRU SPARE RIG.

11-29-04: TIH TO 4130. (TOP OF FISH)

11-30-04: TIH W/2 7/8" TBG TO 4130. JAR DN ON SUB PUMP. TIH OPEN ENDED 2 7/8" WS TO 4115. SPOT 24 BBLS 15% ACID. PUH TO 2854.

12-01-04: TIH W/SHOE, BMPR SUB, JARS, DC'S & WS. TAG FISH @ 4130.D/O FISH. PUH TO 2854.

12-02-04: TIH W/FLAT BTM MILL, BS, JARS, DC'S & WS TO TAG @ 4130. PUSH MOTOR TO 4545. PUH TO 2554.

12-03-04: PU MILL TO 4003. MILL FR 4003-4445. C/O LINER.

12-06-04: PU NEW 2 3/8" PROD TBG, 40 JTS TO 1263.

12-07-04: TIH W/2 3/8" TBG & SUB PUMP. BTM OF PUMPT @ 4308. START WELL. GOOD PUMP ACTION.

12-08-04: RIG DOWN. FINAL REPORT

| I hereby certify that the information above is true and complete to the based my keepwedge and belief. | |
|--|----------------------------|
| SIGNATURE TITLE Regulatory Specialist | DATE12/10/2004 |
| TYPE OR PRINT NAME Denise Leake | Telephone No. 915-687-7375 |

OC FIELD REPRESENTATIVE II/STAFF MANAGER DEC 2 2 2004