

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02957
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	857943
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	76
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH ROAD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>L</u> : <u>1985</u> Feet From The <u>SOUTH</u> Line and <u>620</u> Feet From The <u>WEST</u> Line Section <u>31</u> Township <u>17S</u> Range <u>35E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ ACIDIZE - TURN TO FLOWING WELL

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-22-04: MIRU PU.

11-23-04: PUMP 60 BBLs 10# BRINE DN CSG & 20 BBLs TBG TO KILL WELL. TIH W/BIT & TAG @ 4676. NO FILL. PUH TO 2500.

11-24-04: PU PKR. PUH OUT OF LINER. LEAVE PKR RELEASED.

11-29-04: TIH W/2 3/8" TBG TO 4324. SET PKR @ 4324. STIMULATE PERFS 4361-4674 W/3000 GALS DAD 15% ACID.

11-30-04: RU SWAB. FLOW WELL TO TANK. SI CONNECT FLOW LINE TO FLOW WELL TO BATTERY. 24 HR TEST SHOWS 39 OIL, 596 WATER, & 625 MCF.

12-01-04: WELL FLOWING TO BATTERY W/180 PSI. RIG DOWN. TURN WELL OVER TO PRODUCTION.

FINAL REPORT



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Leake TITLE Regulatory Specialist

DATE 12/6/2004

TYPE OR PRINT NAME

Denise Leake

Telephone No. 915-687-7375

(This space for State Use)

APPROVED Shirley W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER

CONDITIONS OF APPROVAL, IF ANY:

DATE

DEC 22 2004

DeSoto/Nichols 12-93 ver 1.0