

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 33816
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	UNITED ROYALTY 'A'
8. Well No.	6
9. Pool Name or Wildcat	NORTH DOLLARHIDE FUSSELMAN

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>K</u> : <u>2311</u> Feet From The <u>SOUTH</u> Line and <u>1880</u> Feet From The <u>WEST</u> Line Section <u>19</u> Township <u>24-S</u> Range <u>38-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3160'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>
OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>
	REQUEST TA STATUS <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-12-98: MIRU. SET NEW ANCHOR. BLED WELL DN. NDWH. NUBOP. TOH W/2 7/8" TBG. LD SUB PMP & MOTORS. TIH W/GAUGE RING TO 9030'.
TIH W/CIBP & SET @ 8991'. (71' ABOVE TOP PERF).

10-13-98: TIH W/2 7/8" TBG OPEN ENDED TO 8848'. RU KILL TRUCK & CATCH TRUCK & CIRC HLE W/190 BFW W/PKR FLUID. ATTEMPT TO TEST CSG. TEST TO 500#. LOST 65# IN 30 MINS. TEST TO 300#. LOST 45# IN 30 MIN.

10-14-98: PRESS CSG TO 380# FOR 30 MINS. LOST 65# IN 30 MINS. TOH W/TBG. TIH W/BAILER & DUMP 35' CMT ON TOP OF CIBP @ 8991'. NEW PBTD OF 8956'. RDWL. RE-PRESS CSG TO 580# & CHART FOR NMOCDF FOR 30 MINS. LOST 5#-OK. TIH W/2 7/8" TBG. TOH. LD 2 7/8" TBG.

10-15-98: NDBOP. NUWH. RIG DOWN. WELL IS ASD-RFD (TA'D) ORIGINAL CHART ATTACHED & COPY OF CHART ON BACK.

FINAL REPORT

Dr's Approval of Temporary
Abandonment Expires

1/8/2004

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 10/19/98

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS
APPROVED BY DISTRICT I SUPERVISOR TITLE DATE JAN 08 1999

CONDITIONS OF APPROVAL, IF ANY:

JCBN

22