## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVATION DIVISION	Reviseu 3-27-2004
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240	1220 South St. Francis Dr.	WELL API NO.
· · ·	Santa Fe, NM 87505	30-025-05490
DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210		5. Indicate Type of Lease
DISTRICT III		STATE X FEE 6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410		U. State Off & Gas Lease No.
SUNDRY NO	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PR	ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	NORTH HOBBS (G/SA) UNIT
	APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
1. Type of Well: Oil Well X	Gas Well Other	8. Well No. 341
2. Name of Operator	Cas wer	9. OGRID No. 157984
Occidental Permian Ltd.		
3. Address of Operator	NIM 99240 505/207 9200	10. Pool name or Wildcat HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, 4. Well Location	NM 88240 505/397-8200	
Unit Letter O: 330	Feet From The SOUTH 2310 Fee	t From The EAST Line
Section 24	Township 18-S Range 37-E	
	11. Elevation (Show whether DF, RKB, RT GR, etc.)	LEA County
Dit on Deleve and Trule April at		
Pit or Below-grade Tank Application or Closure  Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
· —		
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material  12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OPN	
PULL OR ALTER CASING	Multiple Completion CASING TEST AND CEMEN	
OTHER: Re-Activate and acidize	OTHER:	1308
The Fred value and actualize		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed work) 522 Robb 1703. For Manaple Completions. Attach wendore diagram of proposed completion of recompletion.		
1. DO CIBP @ 3870		
<ul><li>2. Acidize perfs 4186-4258</li><li>3. Run production equipment</li></ul>		
3. Run production equipment		
Harter Control Of the Control		
closed according to NMOCD guidelines	and complete to the best of my knowledge and belief. I further certify that	t any pit or below-grade tank has been/will be constructed or
SIGNATURE SIGNATURE	<u> </u>	/ /
	TITLE Engineering Adv	
TYPE OR PRINT NAME David Nelson For State Use Only		TELEPHONE NO.
· <i>1</i> 7	OC FIELD REPRESENTAT	IVE II/STAFF MAINACES JAN 1 3 200
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL IF ANY		