## New Mexico Oil Conservation Division, District 1

1625 N. French Drive

Form 3160-5 (June 1990)

## UNITED STATESHODDS, NM 88240 DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993 **BUREAU OF LAND MANAGEMENT** 5. Lease Designation and Serial No. NM-13276 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE I. Type of Well Oil Gas Well Other 8. Well Name and No. 2. Name of Operator Greenstone Fed Com 1 Dominion Oklahoma Texas E&P, Inc. 9. API Well No. 3. Address and Telephone No. 30-025-34677 14000 Quail Springs Parkway, Oklahoma City, OK 73134 (405) 749-526810. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Wildcat Atoka 480' FSL & 1600' FEL, Sec. 19, T20S, R34E 11. County or Parish, State Lea County, NM 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recognition New Construction Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice **Altering Casing** Conversion to Injection approved as to plugging of the well bota Dispose Water Dability under bond is ratained until Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* 1. 12-10-04 MIRU. 2. 12-14-04 Set 5-1/2" CIBP @ 12480', 2 runs w/ dumpbailer. 3. 12-15-04 Tag TOC @ 12410' w/ tbg. & circ. well w/ 10# MLF. 4. 12-15-04 Spot 25 sx cmt. @ 10500' type H 15.5# per gallon. 5. 12-15-04 Spot 25 sx cmt. @ 8576', 50' below DV tool, 50' above DV tool w/ type H cmt. 6. 12-16-04 Spot 25 sx cmt. @ 5565' WOC & tag @ 5137'. 7. 12-16-04 Perf. & sqz. well w/ 35 sx cmt. @ 2 BPM @ 800# SI @ 1600#. 8. 12-17-04 Tag TOC @ 3026'. 9. 12-17-04 Perf. well @ 570', set pkr. @ 30' sqz. 155 sx cmt. 570' to surface, 5-1/2" 10. 12-17-04 Spot 10 sx cmt. 85' to surface inside 5-1/2". 11. RDMO. Install dry hole marker & clean location. APPROVED 4 2005 JAN 14. I hereby certify that the foregoing is true and correct PETROLEUM ENGINEER Signed Agent Date 12-21-04 (This space for Federal or State office Approved by Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements

