

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. <u>30-025-23572</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. <u>LC 032326B</u>
7. Lease Name or Unit Agreement Name <u>Langlie Mattiv Woolworth Unit</u>
8. Well Number <u>165</u>
9. OGRID Number
10. Pool name or Wildcat <u>Langlie Mattix 7 Rivers / Queen</u> <u>Grangerburg</u>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other X

2. Name of Operator
Betwell Oil & Gas

3. Address of Operator
P.O. Box 22577 Hialeah, Florida 33012

4. Well Location
Unit Letter N : 2310 feet from the West line and 330 feet from the South line
Section 34 Township 24S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL _____ Sect _____ Twp _____ Rng _____ Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____
Distance from nearest surface water _____ Below-grade Tank Location UL _____ Sect _____ Twp _____ Rng _____ ;
_____ feet from the _____ line and _____ feet from the _____ line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Rickey Smith TITLE Agent Foreman DATE 1-19-05

Type or print name Rickey Smith E-mail address: _____ Telephone No. 432-586-3076

(This space for State use)

APPROVED BY Langlie Wink TITLE OCD FIELD REPRESENTATIVE II/STAFF MANAGER DATE _____
Conditions of approval, if any:

JAN 25 2005

MAYO MARRS CASING PULLING INC.
BOX 863
KERMIT, TEXAS 79745

BETWELL OIL & GAS

Lease: LANGLEIE MATTIX WOOLWORTH UNIT # 165
Project: P & A – CEMENTING REPORT

07-09-04 - SPOT 25 SXS @ 3240'-2920' & TAG
07-09-04 – PERFORATE @ 2000'
07-09-04 - SQUEEZE 25 SXS @ 2000'-1814' & TAG
07-12-04 – PERFORATE @ 1000' – 2800# TEST
07-12-04 - SPOT 35 SXS @ 1000'-630' & TAG
07-12-04 - SPOT 10 SXS @ 100' TO SURFACE

INSTALL DRY HOLE MARKER
CIRCULATE 10# MUD