

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. <u>30-025-11341-0000</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. <u>LC-03326 B</u>
7. Lease Name or Unit Agreement Name <u>Langlie Mattiv Woolworth Unit</u>
8. Well Number <u>142</u>
9. OGRID Number
10. Pool name or Wildcat <u>Langlie Mattiv 7 Rivers/Green</u>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other IN

2. Name of Operator
Betwell Oil & Gas

3. Address of Operator
P.O. Box 22577 Hialeah, Florida 33012

4. Well Location

Unit Letter L : 2310 feet from the SOUTH line and 990 feet from the West line
Section 34 Township 24S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3182

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL _____ Sect _____ Twp _____ Rng _____ Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____
Distance from nearest surface water _____ Below-grade Tank Location UL _____ Sect _____ Twp _____ Rng _____ ;
feet from the _____ line and _____ feet from the _____ line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Rickey Smith TITLE Agent DATE 1-28-05

Type or print name Rickey Smith E-mail address: _____ Telephone No. 432-586-3076

(This space for State use)

APPROVED BY Gayle Wink TITLE _____ DATE FEB 01 2005

Conditions of approval, if any:

OCD FIELD REPRESENTATIVE II/STAFF MANAGER

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

MAYO MARRS CASING PULLING INC.
BOX 863
KERMIT, TEXAS 79745

BETWELL OIL & GAS

Lease: LANGLEIE MATTIX WOOLWORTH UNIT # 142

Project: P & A - CEMENTING REPORT

01-18-05 - SET 7" CIBP @ 3275'-SPOT 30 SXS ON TOP-3094'
01-19-05 - SPOT 30 SXS @ 2695'-2515'
01-19-05- PERFORATE @ 1486' - SQUEEZE 35 SXS - TAG @ 1324'
01-20-05 - PERFORATE @ 1150' - SQUEEZE 35 SXS - TAG @ 1000'
01-20-05 - PERFORATE @ 300' - SQUEEZE 150 SXS - TAG @ 307'
01-21-05 - SQUEEZE 50 SXS @ 300'-189' & TAG
01-24-05 - PERFORATE @ 185' - SQUEEZE 40 SXS - TAG @ 50'
01-24-05 - SPOT 15 SXS @ 50' TO SURFACE

INSTALL DRY HOLE MARKER
CIRCULATE 10# MUD