

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Conservation Division
1626 N. Front St.
Hobbs, NM 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

TEXACO EXPLORATION & PRODUCTION INC.

3. Address and Telephone No.

P.O. Box 3109 MIDLAND, TX 79702 (915) 688-4438

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UNIT LETTER J, 1650 FSL, 1980 FEL, SEC. 19
TOWNSHIP 24-S, RANGE 38-E,

5. Lease Designation and Serial No.

Nm 0349952

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No. WEST DOLLARHIDE

DRINKARD UNIT #7

9. API Well No.

30-025-12215

10. Field and Pool, or Exploratory Area

WEST DOLLARHIDE
DRINKARD TUBBS, QUEEN

11. County or Parish, State

LEA, NEW MEXICO

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. SET 5 1/2" CIBP @ 6500', Spot 25 SX Plug 6500'-6300' (Drinkard)
2. DISPLACE HOLE w/ SALT GEL MUD, 9.5# Brine w/ 25 # GEL P/BBL.
3. Spot 25 SX Plug 6275'-6175' (TUBBS)
4. PERF 6 HOLES @ 3802, SQUEEZE 40 SXs (QUEENS PERFS) WOC TAG @ 346
5. PERF 6 HOLES @ 3300, SQUEEZE 40 SXs (8 5/8 SHOE) WOC TAG 3178'
6. PERF 6 HOLES @ 2727, SQUEEZE 60 SXs (B-SALT) WOC TAG 2200'
7. PERF 6 HOLES @ 1426, SQUEEZE 60 SXs (T-SALT) WOC TAG 1320'
8. PERF 6 HOLES @ 50, CIRC 75 SXs CMT 5 1/2" X 8 5/8 ANNULUS
9. INSTALL DEQ HOLE MARKER, CLEAN LOC. 5/1/00 per JO Wann

14. I hereby certify that the foregoing is true and correct

Signed Poly Alvarez

Title VICE-PRESIDENT

(915)

683-4996

Date 5/1/00

(This space for Federal or State office use)

Approved (ORIG. SGD.) GARY GOURLEY
Conditions of approval, if any:

Title

PETROLEUM ENGINEER

Date

MAY 19 2000

**PLUGGER'S
DAILY WORK RECORD**

 P.O. BOX 5024
 MIDLAND, TEXAS 79704
 (915) 683-4996

CUSTOMER NAME <i>Texaco CIP Tar</i>		CUSTOMER NO.	DATE <i>4-25-00</i>	DAY OF WEEK <i>Tue</i>	PLUGGER'S UNIT NO. <i>Rig #2</i>	JOB NO.
LEASE <i>West Dallarhale Drinkard Unit</i>				WELL NO. <i>7</i>		
COUNTY <i>Lea</i>		FIELD <i>Queen</i>		LEGAL DESCRIPTION OF LEASE <i>21 M 0349852</i>		
FROM		TO		DESCRIBE WORK TO 1/2 HOUR - SEPARATE EACH OPERATION		
W O R K				Held Safety Meeting on Air Hoses, tools & Equip Road Rig i		
				Equip to loc. Mr. Alu Rig & Has Equip CR - SETTL on East side		
				to SETT on West side Had Flow of water 5 TCF - 10		
				pull on East side 20 ft over w/ TBG Jump POH w/ TBG		
				No sub Head Robs in hole C/O Equip Pulled POH w/ TBG		
				Road w/ 150 - 518 Rool & pump C/O Equip Pr TBG CONT to POH		
				TBG w/ 117 54 2' 116 TBG pull on West attempt to		
				Release PKR pull up on TBG & lower Tag same spot		
				pull up on TBG & Rotate same Result POH w/ TBG w/ 10		
				excess left kill string in hole		
D E S C R I P T I O N				SWIFT - NO - Accident		
				Notified Andy w/ Blum		
				NO - 000413 080400 52		
				(NO - 000413 080400 52)		