

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, Result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	☒	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

September 25, 1953
(Date)Midland, Texas
(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

The Texas Company

(Company or Operator)

E. M. Byers

(Lease)

Blount Drilling Company

(Contractor)

Well No. 1 in the NW 1/4 SW 1/4 of Sec. 19

T. 24-S, R. 38-E, NMPM, Wildcat

Pool, Lea

County.

The Dates of this work were as follows: See Below

Notice of intention to do the work ~~was~~ (was not) submitted on Form C-102 on _____, 19____

(Cross out incorrect words)

and approval of the proposed plan ~~was~~ (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

TD: 6686'

Ran and cemented 205 joints 6676' of 5½" casing at 6686' with 200 sacks. Completed 12:30 A. M. 9-21-53.

Commenced drilling cement plug 1:00 P. M. 9-22-53. Tested cement job by pressure method. Tested okay.

Witnessed by _____ (Name) _____ (Company) _____ (Title)

Approved:

OIL CONSERVATION COMMISSION

Engineer District 1

(Title)

SEP 28 1953

(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name _____

Position Asst. Dist. Supt.

Representing The Texas Company

Address Box 1270, Midland, Texas