Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103 May 27, 2004
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II	30-025-05278
District III 1301 W. Grand Ave., Artesia, NM 88210 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE X 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM	, v,
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	J. M. Denton
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 4
2. Name of Operator	9. OGRID Number
Brothers Production Company Inc.	2936
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 7515, Midland, TX 79708	Denton Devonian
4. Well Location Unit Letter K: 1980 feet from the South line and 2080 feet from the West line	
Unit Letter K: 1980 feet from the South line and 2080 feet from the West line Section 11 Township 15-S Range 37E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	The second secon
GR: 4005' KB: 4017'	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	
PULL OR ALTER CASING. MULTIPLE COMPLETED CASING/CEMENT JOB 20 1 1 1 1 1 1 1 1 1	
FIGURE OF THE PROPERTY OF THE	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion.	
1. MIRU PU. Install BOP.	
2. POOH w/ 2-7/8" tbg.	
3. RU Wireline. RIH w/ 5-1/2" 17# and 20# CIBP. Set CIBP @ 11,130".	
4. POOH W/ Wireline. RIH w/ dump bailer. Dump bail 35' of cmnt on CIBP.	
5. RDMO wireline.	
	re test casing to 500 psig.
12000110 Control of the control of t	
	1. 1000
	No.
	The state of the s
	15.5 8.2 1.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .	
SIGNATURE Nany M. Brock TITLE Production Superintendent DATE 1-10-05	
Type or print name OC FIELD TRAPAGESTATIVE II/STAFF MANAGE Felephone No.	
Type or print name OF FIELD RAIP BEST ATIVE 11/5 TAFF MANAGETFELEPHONE No. For State Use Only	
$\mathcal{H}_{\mathcal{A}}$	
APPROVED BY: TITLE TITLE	DAPEB 1 7 2005