Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office May 27, 2004 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-025-21342 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE 🖂 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 VA-0452 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Alphabet AOR State DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number Yates Petroleum Corporation 025575 3. Address of Operator 10. Pool name or Wildcat 105 S. 4th Street, Artesia, NM 88210 South Berry Bone Springs/Berry Wolfcamp 4. Well Location Unit Letter 1980 1980 F feet from the North line and feet from the West line Section 17 Township **21S** Range **NMPM** Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3735'GR Pit or Below-grade Tank Application or Closure Pit type <u>Steel</u> Depth to Groundwater <u>>100'</u> Distance from nearest fresh water well <u>N/A</u> Distance from nearest surface water \_\_\_\_ Pit Liner Thickness: Below-Grade Tank: Volume bbls: Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PERFORM REMEDIAL WORK □ REMEDIAL WORK ALTERING CASING □ COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS  $\Box$ ÉASING/CEMENT JOB PULL OR ALTER CASING MULTIPLE COMPL OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Asiach wellbore diagram of proposed completion or recompletion. 1-24-05 Set 7" CIBP at 12194' with 35' cement on top. Set 7" CIBP at 9189' with 35' cement on top. 1-26-05 Perforated casing at 6300'. RIH and set packer @ 5800'. 1-27-05 Squeezed w/45 sx @ 6300'. WOC. Tagged plug @ 6194'. Perforated casing at 5900'. Set packer @ 5580'. 1-28-05 Squeezed w/60 sx @ 5900'. WOC. Tagged plug @ 5767'. Perforated casing at 3975'. Set packer @ 3655'. Squeezed w/40 sx. 1-31-05 Tagged plug @ 3849'. Perforated casing at 1878'. Set packer @ 1612'. Squeezed w/40 sx. WOC. Tagged plug @ 1776'. Perforated casing at 454'. Set packer @ 155'. Squeezed w/40 sx. WOC. 2-2-05 Tagged plug @ 338'. Perforated casing at 60'. Squeezed 20 sx to surface. Cut off wellhead and installed dry-hole marker. Approved as to plugging of the Well Bore. WELL IS PLUGGED AND ABANDONED. FINAL REPORT. Liability under bond is retained until surface restoration is completed. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines \_, a general permit \_ or an (attached) alternative OCD-approved plan \_. E-mail address: stormid@ypcnm.com

Telep...

T **SIGNATURE** Type or print name Stormi Davis For State Use Only APPROVED BY:

Conditions of Approval (if any)