STATE OF NEW MEXICO RGY AND MINERALS DEPARTMENT	
DIL CONSERVATION DIVISION	V
DISTRIBUTION P. O. BOX 2088	Form C-103
	Revised 10-1-78
SANTA FE, NEW MEXICO 87501	
U.s.a.s.	5a. Indicate Type of Lease
LAND OFFICE	State X Fee
OPERATOR 0 1000	5. State Oil & Gas Lease No.
SEP 2 2 1986 Will	0G-3931
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DALLE ON TO DEEPEN ON SULE PROPOSALS.) (DO NOT USE "APPLICATION FOR PERMIT -" FORM C-1011 FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL X GAS OTHER-	j
me of Operator	8. Farm or Lease Name
Chevron U.S.A. Inc.	Lea "KN" State
dress of Operator	9. Well No.
P.O. Box 670 Hobbs, NM 88240	2
B 990 North 1650	10. Field and Pool, or Wildcat Midway Abo
East 17 17S 37E	RMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3783 GL	12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report Notice of Intention to: ORM REMEDIAL WORK POMARILY ABANDON OR ALTER CASING CHANGE PLANS CHANGE PLANS OTHER	ALTERING CASING DOLLING DELUG AND ABANDONMENT
Clarky state all positions design and sine positions design	in the second day of static and proposed

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed park) SEE RULE 1703.

Well is currently uneconmic to produce and is shut-in with a rod part. Set CIBP 3 8750' and cap with 35' of cement. Circulate wellbore with packer fluid. Test casing and CIBP to 500 psi for 30 minutes. Remove production equipment. Change status to temporaily abandoned.

	TEMPORARY ABANDON 44	87 7-18-18
nereby certify that the information abov	e is true and complete to the best of my knowledge and belief.	<u></u>
, T. H. Bull	Division Drilling Manager	9-16-1986
Jerry	DISTRICT 1 SUPERVISOR	SEP 1 8 1986.
ITIONS OF APPROVAL, IF ANY		