## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION			
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-26935		
DISTRICT II	,		5. Indicate Type of Lease		
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE	
DISTRICT III			6. State Oil & Gas Lease No.		
1000 Rio Brazos Rd, Aztec, NM 87410			7 Y NI I Init A concessor	Nama	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			NORTH HOBBS (G/SA) UN	NIT	
1. Type of Well:			8. Well No. 232		
Oil Well Gas Well Other Wtr Injector					
2. Name of Operator			9. OGRID No. 157984		
Occidental Permian Ltd.			10. Pool name or Wildcat	HOBBS (G/SA)	
3. Address of Operator 1017 W. Stanolind Rd., HOBBS, N	M 88240 505/397-82	200	10.1 oor hallse or windeat	HOBBS (G/SA)	
4. Well Location	1 00240				
Unit Letter K : 1400	Feet From The SOUTH	1370	Feet From The WEST	Line	
	<del></del>			I.T.A. Courte	
Section 30	Township 18-S  11. Elevation (Show whether DF, RKB,	<del></del>	B-E NMPM	LEA County	
	3650 GL	KI GR, etc.)			
Pit or Below-grade Tank Application	or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING (	CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OF	NS. PLUG & AB	ANDONMENT	
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEME	NT JOB		
OTHER: Squeeze, open pay, and stir	mulate	OTHER:			
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)					
SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
1. Pull equipment and squeeze 4138-58.					
2. Perforate 4204-10. 3. Acid stimulate.					
4. Run CO2 injection equipment.					
Establish injector as produced gas injector under section 18, page 12 of Division Order R-6199-B.					
			Teg.	12	
			600		
I hereby certify that the information above is true	and complete to the best of my knowledge ar	nd belief. I further certify that any	pit or below-grade tank has been/will be	constructed or	
closed according to NMOCD quidelines	, a general permit	or an (attached) alternat			
SIGNATURE X / , )		TITLE Engineering A	Advisor DATE	2-25-05	
TYPE OR PRINT NAME David Nelson	n E-mail address:		TELEPHONE NO.	505-397-8200	
For State Use Only	1 D-man address.			305 577 3200	
$\Psi$	) Li ) Las h	דודו ב	DAT	E MAD OO -	
APPROVED BY LAND	OC FIELD	O KEPKESENTATIVE II,	STAFE MANIA CER	E <u>MAR 0 2 2005</u>	
CONDITIONS OF APPROVAL IF ANY:			THE MANAGES	_	