

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.

30-025-36452

5. Indicate Type of Lease

STATE ☐ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Cuerno 4 State

8. Well Number

2

9. OGRID Number

015742

10. Pool name or Wildcat

Grama Ridge; Morrow, East

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Nearburg Producing Company

3. Address of Operator

3300 N. A St., Bldg. 2, Ste. 120, Midland, TX 79705

4. Well Location

Unit Letter B : 736 feet from the North line and 1899 feet from the East line

Section 4 Township 22S Range 35E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3605' GR

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well

Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;

 feet from the line and feet from the line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 8-18-04 Cap pkr. w/ blanking plug & 6 sx cmt. 10,900', calc. TOC @ 10,865'. 8-18-04 Set 7" CIBP @ 9170', cap w/ 6 sx cmt. TOC calc. @ 9135'. Stub plug @ 8200', WOC & tag 8-25-04 @ 8079' w/35 sx cmt. PUH to 6950' spot 35 sx cmt. TOC calc. @ 6850'. PUH to 5631', spot 60 sx WOC & tag @ 5420'. Spot 35 sx cmt. @ 2531', TOC calc. @ 2431'. Spot 35 sx cmt. @ 1538', WOC & tag @ 1435'. Spot 35 sx cmt. @ 500', TOC calc. @ 400'. Spot 10 sx from 15' to surface. RDMO. Install dry hole marker & clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Roger Massey TITLE Agent DATE 9-02-04

Type or print name Roger Massey E-mail address: Telephone No. (432) 530-0907

(This space for State use)

APPROVED BY [Signature] TITLE DATE 3-4-2005

Conditions of approval, if any:

PETROLEUM ENGINEER